

INSPECTION SHEET 検品書
EXCAVATOR バックホー

INSPECTION DATE	2025/4/9	MAKE	HITACHI	MODEL	ZX225USR-5B
SERIAL	HCMDCQA0H00302201			STAMP	HCMDCQA0H00302201
HR METER	8983	HR	YEAR	YR	
CAB/CNP	ROPS CAB / CAB / ROPS CNP / CNP / NONE			SHOE	600G

ENGINE : MODEL		4HK1	S/N
Oil leakage	FAIR	Attn	
Blow-By	FAIR	Attn	A LITTLE • MIDDLE • SEVERE
Sound	FAIR	Attn	
Oil	FAIR	Attn	
Exhaust Color	FAIR	Attn	
US EPA	YES	NO	
MAIN PUMP			
Sound	FAIR	Attn	
Oil leakage	FAIR	Attn	
Power	FAIR	Attn	
COOLING SYSTEM			
Radiator	FAIR	Attn	
Oil Cooler	FAIR	Attn	
OPERATING SYSTEM			
Swing	FAIR	Attn	ガタあり SWING: LOOSE
Travel	FAIR	Attn	*1
INTERIOR See Photos. 写真参照			
INTERIOR COND.	CLEAN	FAIR	DIRTY
Operator's Seat	FAIR	Attn	破れあり TORN
Glasses	FAIR	Attn	
AirCon	A/C	H/C	H only • C only • None
BOOM / ARM / BKT			
Boom	FAIR	Attn	
Boom Cylinder	FAIR	Attn	
Arm	FAIR	Attn	
Arm Cylinder	FAIR	Attn	
BKT	FAIR	Attn	
BKT Cylinder	FAIR	Attn	

UNDERCARRIAGE : See Photos. 写真参照	
RUST (5: NONE, 4: A LITTLE, 3: MIDDLE, 2: MUCH, 1: CORRODED)	3
COMMENT	
BKT (STD / SLOPE / NARROW / SKELETON / OTHER ()	
Lever	LONG • WRIST
Multi	MULTI • 2 • NO
ARM-CRANE	YES • NO
BLADE	YES • NO
OFFSET	YES • NO
OFFSET Cylinder	FAIR • Attn
Piping	YES • NO Breaker only • Multi
COMMENT	
コントロールバルブ周りのホース接触して音あり	
SOME HOSES AROUND CONTROL VALVE:	
NOISES WITH BUMPING OTHER HOSES	
A/Cベルト鳴きあり、冷えない A/C BELT: NOISES, A/C: MALFUNCTION	
*1 右クローラー動き悪い、1~2秒くらいで引っかかるような感じで止まる	
*1 RIGHT TRACK:	
STOPPING LIKE GETTING CAUGHT ON SOMETHING	
IN A COUPLE OF SECONDS	
AFTER STARTING TO TRAVEL	
RUST of BODY (5: NONE, 4: A LITTLE, 3: MIDDLE, 2: MUCH, 1: CORRODED)	3

This inspection information is for reference only at "the inspection date" by SOGO. NOT to guarantee the condition of the actual machine.

この査定情報は『点検日時点』での参考資料であり、実際の機械の状態を保証するものではありません。