

INSPECTION SHEET 検品書
EXCAVATOR バックホー

INSPECTION DATE	2025/4/9	MAKE	KOMATSU	MODEL	PC128US-8
SERIAL	24321		STAMP	KMTPC189T01024321	
HR METER	7912	HR	YEAR	YR	
CAB/CNP	ROPS CAB / CAB / ROPS CNP / CNP / NONE		SHOE	500G	

ENGINE : MODEL 4D95LE-5 **S/N** 508165

Oil leakage	FAIR	Attn	
Blow-By	FAIR	Attn	A LITTLE · MIDDLE · SEVERE
Sound	FAIR	Attn	
Oil	FAIR	Attn	
Exhaust Color	FAIR	Attn	
US EPA	YES	NO	

MAIN PUMP

Sound	FAIR	Attn	
Oil leakage	FAIR	Attn	
Power	FAIR	Attn	

COOLING SYSTEM

Radiator	FAIR	Attn	
Oil Cooler	FAIR	Attn	

OPERATING SYSTEM

Swing	FAIR	Attn	ゴリゴリ感あり RATTLING
Travel	FAIR	Attn	

INTERIOR See Photos. 写真参照

INTERIOR COND.	CLEAN · FAIR · DIRTY
Operator's Seat	FAIR · Attn 破れあり TORN
Glasses	FAIR · Attn 枠にサビあり WINDSHIELD FRAMES: CORRODED
AirCon	A/C · H/C · H only · C only · None

BOOM / ARM / BKT

Boom	FAIR	Attn	
Boom Cylinder	FAIR	Attn	左右にじみあり CYLINDERS: OIL OOZING
Arm	FAIR	Attn	
Arm Cylinder	FAIR	Attn	にじみあり OIL OOZING
BKT	FAIR	Attn	
BKT Cylinder	FAIR	Attn	油漏れ小 OIL LEAKING

UNDERCARRIAGE : See Photos. 写真参照

RUST (5: NONE, 4: A LITTLE, 3: MIDDLE, 2: MUCH, 1: CORRODED)	2
--	---

COMMENT

スイベル油漏れあり SWIVEL: OIL LEAKING

BKT	STD / SLOPE / NARROW / SKELETON / OTHER ()
-----	---

Lever	LONG · WRIST
-------	--------------

Multi	MULTI · 2 · NO
-------	----------------

ARM-CRANE	YES · NO
-----------	----------

BLADE	YES · NO
-------	----------

OFFSET	YES · NO
--------	----------

OFFSET Cylinder	FAIR · Attn
-----------------	-------------

Piping	YES · NO Breaker only · Multi
--------	-------------------------------

COMMENT

右サイドカバー変形あり RIGHT SIDE COVER: DISTORTED

A/Cエラー表示あり A/C ERROR DISPLAY

RUST of BODY (5: NONE, 4: A LITTLE, 3: MIDDLE, 2: MUCH, 1: CORRODED)	2
--	---

This inspection information is for reference only at "the inspection date" by SOGO. NOT to guarantee the condition of the actual machine.

この査定情報は『点検日時点』での参考資料であり、実際の機械の状態を保証するものではありません。