

INSPECTION SHEET 検品書
EXCAVATOR バックホー

INSPECTION DATE	2025/3/31	MAKE	KOMATSU	MODEL	PC30MR-3
SERIAL	41371		STAMP	KMTPC200JFE041371	
HR METER	2585	HR	YEAR	YR	
CAB/CNP	ROPS CAB / CAB / <u>ROPS CNP</u> / CNP / NONE		SHOE	300R	

ENGINE : MODEL		S/N
Oil leakage	FAIR · Attn	
Blow-By	FAIR · Attn	A LITTLE · MIDDLE · SEVERE
Sound	FAIR · Attn	
Oil	FAIR · Attn	
Exhaust Color	FAIR · Attn	
US EPA	YES · NO	
MAIN PUMP		
Sound	FAIR · Attn	
Oil leakage	FAIR · Attn	
Power	FAIR · Attn	
COOLING SYSTEM		
Radiator	FAIR · Attn	
Oil Cooler	FAIR · Attn	
OPERATING SYSTEM		
Swing	FAIR · Attn	
Travel	FAIR · Attn	
INTERIOR See Photos. 写真参照		
INTERIOR COND.	CLEAN · FAIR · DIRTY	
Operator's Seat	FAIR · Attn	
Glasses	FAIR · Attn	
AirCon	A/C · H/C · H only · C only · None	
BOOM / ARM / BKT		
Boom	FAIR · Attn	ガタあり LOOSE
Boom Cylinder	FAIR · Attn	にじみあり OIL OOZING
Arm	FAIR · Attn	
Arm Cylinder	FAIR · Attn	
BKT	FAIR · Attn	
BKT Cylinder	FAIR · Attn	

UNDERCARRIAGE : See Photos. 写真参照					
RUST (5: NONE, 4: A LITTLE, 3: MIDDLE, 2: MUCH, 1: CORRODED)					4
COMMENT 					
BKT	(STD / SLOPE / NARROW / SKELETON / OTHER()				
Lever	LONG ▪ (WRIST)				
Multi	MULTI ▪ 2 ▪ (NO)				
ARM-CRANE	YES ▪ (NO)				
BLADE	(YES) ▪ NO				
OFFSET	YES ▪ (NO)				
OFFSET Cylinder	FAIR ▪ Attn				
Piping	YES ▪ (NO)	Breaker only ▪ Multi			
COMMENT 					
RUST of BODY (5: NONE, 4: A LITTLE, 3: MIDDLE, 2: MUCH, 1: CORRODED)					4

This inspection information is for reference only at "the inspection date" by SOGO. NOT to guarantee the condition of the actual machine.

この査定情報は『点検日時点』での参考資料であり、実際の機械の状態を保証するものではありません。