

INSPECTION SHEET 検品書
WHEEL LOADER タイヤショベル

INSPECTION DATE	2025/6/10	MAKE	KOMATSU	MODEL	WA380-5
SERIAL	61243		STAMP	W097-61243	
HR METER	10635	HR	Odometer	28183	km
CAB/CNP	ROPS CAB / CAB / ROPS CNP / CNP / NONE			TIRE SIZE	23.5-25

ENGINE : MODEL		S/N
Oil leakage	☒ FAIR • Attn	
Blow-By	☒ FAIR • Attn	A LITTLE • MIDDLE • SEVERE
Sound	☒ FAIR • Attn	
Oil	☒ FAIR • Attn	
Exhaust Color	☒ FAIR • Attn	
US EPA	☒ YES • NO	
OPERATION PUMP		
Sound	☒ FAIR • Attn	
Oil leakage	☒ FAIR • Attn	
Power	☒ FAIR • Attn	
COOLING SYSTEM		
Radiator	☒ FAIR • Attn	
Oil Cooler	☒ FAIR • Attn	
TRANSMISSION & TRAVEL		
T/M TYPE	☒ PS • DD	
Transmission	☒ FAIR • Attn	
Travel	☒ FAIR • Attn	
FOOT BRAKE	☒ FAIR • Attn	
PARKING BRAKE	☒ FAIR • Attn	
INTERIOR See Photos. 写真参照		
INTERIOR COND.	CLEAN • ☒ FAIR • DIRTY	
Operator's Seat	☒ FAIR • Attn	
Glasses	☒ FAIR • Attn	F、F左割れあり WINDSHIELD: CRACKED
AirCon	☒ A/C • H/C • H only • C only • None	
FRONT & CYLINDERS		
Arm	☒ FAIR • Attn	左右シリンダーサビあり CYLINDERS: RUSTY
Bell crank	☒ FAIR • Attn	
Bucket	☒ FAIR • Attn	
Articulate	☒ FAIR • Attn	

UNDERCARRIAGE : See Photos. 写真参照	
RUST (5: NONE, 4: A LITTLE, 3: MIDDLE, 2: MUCH, 1: CORRODED)	3
TIRE WEAR	☒ FAIR • WORN • UNEVEN WEAR
COMMENT	
STEERING TYPE ☒ WHEEL STEERING / ☐ COMMAND STEERING / ☐ LEVER STEERING	
RIDE CONTROL	☒ YES • NO
ATTACHMENTS	
STD BKT	☒ YES • OTHER
BLADE	YES • ☒ NO Piping for Tilt YES • ☒ NO
COMMENT	
左サイドカバー変形、閉まらない	
LEFT SIDE COVER: DISTORTED, UNABLE TO SHUT	
E01表示あり "E01" ERROR DISPLAY	
RUST of BODY (5: NONE, 4: A LITTLE, 3: MIDDLE, 2: MUCH, 1: CORRODED)	
2	

This inspection information is for reference only at "the inspection date" by SOGO. NOT to guarantee the condition of the actual machine.
この査定情報は『点検日時点』での参考資料であり、実際の機械の状態を保証するものではありません。