

INSPECTION SHEET 検品書
EXCAVATOR バックホー

INSPECTION DATE	2025/4/22	MAKE	KUBOTA	MODEL	U-40-6E
SERIAL	30837		STAMP	30837	
HR METER	3024	HR	YEAR	YR	
CAB/CNP	(ROPS CAB) / CAB / ROPS CNP / CNP / NONE		SHOE	350G PADS	

ENGINE : MODEL		D1803	S/N	7JE6479
Oil leakage	FAIR · Attn			
Blow-By	FAIR · Attn	A LITTLE · MIDDLE · SEVERE		
Sound	FAIR · Attn			
Oil	FAIR · Attn			
Exhaust Color	FAIR · Attn			
US EPA	YES · NO			
MAIN PUMP				
Sound	FAIR · Attn			
Oil leakage	FAIR · Attn			
Power	FAIR · Attn			
COOLING SYSTEM				
Radiator	FAIR · Attn			
Oil Cooler	FAIR · Attn			
OPERATING SYSTEM				
Swing	FAIR · Attn			
Travel	FAIR · Attn			
INTERIOR See Photos. 写真参照				
INTERIOR COND.	CLEAN · FAIR · DIRTY			
Operator's Seat	FAIR · Attn	穴あり HOLE		
Glasses	FAIR · Attn			
AirCon	A/C · H/C · H only · C only · None			
BOOM / ARM / BKT				
Boom	FAIR · Attn			
Boom Cylinder	FAIR · Attn			
Arm	FAIR · Attn			
Arm Cylinder	FAIR · Attn			
BKT	FAIR · Attn			
BKT Cylinder	FAIR · Attn			

UNDERCARRIAGE :		See Photos.	写真参照
RUST (5: NONE, 4: A LITTLE, 3: MIDDLE, 2: MUCH, 1: CORRODED)			4
COMMENT			
BKT	(STD / SLOPE / NARROW / SKELETON / OTHER())		
Lever	LONG ▪ (WRIST)		
Multi	MULTI ▪ (2) ▪ NO		
ARM-CRANE	(YES) ▪ NO	*1	
BLADE	(YES) ▪ NO		
OFFSET	YES ▪ (NO)		
OFFSET Cylinder	FAIR ▪ Attn		
Piping	(YES) ▪ NO	Breaker only ▪ (Multi)	
COMMENT			
*1 システムエラー表示あり WARNING DISPLAY FOR SYSTEM			
RUST of BODY (5: NONE, 4: A LITTLE, 3: MIDDLE, 2: MUCH, 1: CORRODED)			3

This inspection information is for reference only at "the inspection date" by SOGO. NOT to guarantee the condition of the actual machine.

この査定情報は『点検日時点』での参考資料であり、実際の機械の状態を保証するものではありません。