## INSPECTION SHEET 検品書 WHEEL LOADER タイヤショベル

INSPECTION DATE		2025/6/4				MAKE		HKN		MODEL		HK130S					
SERIAL	HK130S-50014						STAMP	HK130S-50014									
HR METER	3	550		HR	Odo	ometer		_	ŀ	кm	YEAR					YR	
CAB/CNP	ROPS CA	AB(/	CAB	ROP	S CN	P / CNP /	NONE	TIRE SIZE		•	8.25-	16 14PR	(S	NOW	<b>'</b> )		
ENGINE :	ENGINE : MODEL S/N								UNDERCARRIAGE: See Photos. 写真参照								
Oil leakage	FAIR · (Attn	周りに	じみあり	JAROL	JND E	NGINE: OIL O	OZING	RUST (5: NON	IE, 4: A l	LITTLE	E, 3: MIDE	LE, 2: MUCH	l, 1: C	ORROE	DED)	3	
Blow-By	FAIR · Attn	A LI	TTLE •	MIDDL	E•	SEVERE		TIRE WE	AR	FA	AIR • W	ORN • UI	NEVI	EN WI	EAR		
Sound	FAIR · Attn							COMMENT									
Oil	FAIR · Attn							タコメーター	– TA	СНО	METER	R: 8158km	1				
Exhaust Color	FAIR · Attn																
US EPA	YES ·(NO																
OPERATION PUMP								STEERING	TYP€	WHEEL	. STEERING	OMMAND	STEER	ING / I	LEVE	R STEERING	
Sound	FAIR · Attn							RIDE CON	TROL	YES	• (NO)						
Oil leakage	FAIR · (Attn)	油漏	れあり	OIL L	EAK	ING		ATTACHM	ENTS								
Power	FAIR · Attn							STD BI	(T	YES	OTHER	ロータリー	RO	TARY	SNC	WPLOW	
COOLING	SYSTEM							BLAD	E	YES	• (NO)	Piping for	· Tilt	YES		(N)	
Radiator	FAIR · Attn							COMMENT									
Oil Cooler	FAIR · Attn							*1 左右リフト	シリング	ず一油	漏れあり	J LIFT CY	LINDI	ERS: 0	DIL L	.EAKING	
TRANSMIS	SSION &	TRAV	/EL														
T/M TYPE	PS) · DD																
Transmission	FAIR · Attn																
Travel	FAIR · Attn																
FOOT BRAKE	FAIR · Attn																
PARKING BRAKE	FAIR · Attn																
INTERIOR See Photos. 写真参照																	
INTERIOR COND.	CLEAN	• (	FAIF		D:	IRTY											
Operator's Seat	FAIR · (Attn	破れ	、穴あ	り HU	GE C	UTS, HOLE	S										
Glasses	FAIR · Attn																
AirCon	A/C ·	H/C	· (i	H only	- (	C only •	None										
FRONT & CYLINDERS																	
Arm	FAIR · (Attn	*1															
Bell crank	FAIR · Attn																
Bucket	FAIR · Attn																

This inspection information is for reference only at "the inspection date" by SOGO. NOT to guarantee the condition of the actual machine. この査定情報は『点検日時点』での参考資料であり、実際の機械の状態を保証するものではありません。

RUST of BODY (5: NONE, 4: A LITTLE, 3: MIDDLE, 2: MUCH, 1: CORRODED)

Articulate (FAIR) · Attn