

INSPECTION SHEET 検品書
EXCAVATOR バックホー

INSPECTION DATE	2025/7/16	MAKE	YANMAR	MODEL	VIO40-5B
SERIAL	58654		STAMP	58654	
HR METER	4675 HR		YEAR	YR	
CAB/CNP	ROPS CAB / CAB / ROPS CNP / CNP / NONE		SHOE	350R	

ENGINE : MODEL		S/N	L6576
Oil leakage	FAIR · Attn		
Blow-By	FAIR · Attn	A LITTLE · MIDDLE · SEVERE	
Sound	FAIR · Attn		
Oil	FAIR · Attn		
Exhaust Color	FAIR · Attn		
US EPA	YES · NO		
MAIN PUMP			
Sound	FAIR · Attn		
Oil leakage	FAIR · Attn		
Power	FAIR · Attn		
COOLING SYSTEM			
Radiator	FAIR · Attn		
Oil Cooler	FAIR · Attn		
OPERATING SYSTEM			
Swing	FAIR · Attn		
Travel	FAIR · Attn		
INTERIOR See Photos. 写真参照			
INTERIOR COND.	CLEAN · FAIR · DIRTY		
Operator's Seat	FAIR (Attn)	破れあり CUTS	
Glasses	FAIR · Attn		
AirCon	A/C · H/C · H only · C only · (None)		
BOOM / ARM / BKT			
Boom	FAIR · Attn		
Boom Cylinder	FAIR · Attn		
Arm	FAIR · Attn		
Arm Cylinder	FAIR · Attn		
BKT	FAIR · Attn		
BKT Cylinder	FAIR · Attn		

UNDERCARRIAGE :						See Photos. 写真参照						
RUST (5: NONE, 4: A LITTLE, 3: MIDDLE, 2: MUCH, 1: CORRODED)								3				
COMMENT												
BKT	(STD / SLOPE / NARROW / SKELETON / OTHER()											
Lever	LONG ▪ (WRIST)											
Multi	(MULTI) ▪ 2 ▪ NO											
ARM-CRANE	(YES) ▪ NO	*1										
BLADE	(YES) ▪ NO											
OFFSET	YES ▪ (NO)											
OFFSET Cylinder	FAIR ▪ Attn											
Piping	(YES) ▪ NO	Breaker only ▪ Multi										
COMMENT												
*1 クレーンモニター故障、アラーム作動あり												
*1 MONITOR: MALFUNCTION, WARNING SOUNDS: ON												
RUST of BODY (5: NONE, 4: A LITTLE, 3: MIDDLE, 2: MUCH, 1: CORRODED)									3			

This inspection information is for reference only at "the inspection date" by SOGO. NOT to guarantee the condition of the actual machine.

この査定情報は『点検日時点』での参考資料であり、実際の機械の状態を保証するものではありません。