INSPECTION SHEET 検品書 CARRY DUMP キャリーダンプ

INSPECTION DAT		2025/5/2 MA		N	MOROOKA		MODEL	MST-2200VDR		?
SERIAL	044048			STAMP			NOT FOUND			
HR METER	4933 HR Odometer				ŀ	m YEAR			YR	
CAB/CNP	ROPS CA	AB / CAB / ROP	S CNP / CNP	/ NONE	SHOE		800R	TIRE		
ENGINE :	MAIN FRAME									
Oil leakage	FAIR · Attn				MAIN FL	АМЕ	FAIR • Attr			
Blow-By	FAIR · Attn	A LITTLE · MIDDL	E · SEVERE		VESSEL					
Sound	FAIR · Attn				VESSE	L	FAIR • Attr	*2		
Oil	FAIR · Attn				REAR GATE	TYPE	NORMA	.L • L-	-GATE (FLAT)	
Exhaust Color	FAIR · Attn				REAR G	ATE	FAIR • Attr			
US EPA	YES · NO				UNDERCARRIAGE: See Photos. 写真参照					
OPERATION PUMP					RUST (5: NONE, 4: A LITTLE, 3: MIDDLE, 2: MUCH, 1: CORRODED) 4					
Sound	FAIR · Attn				TIRE WE	AR	FAIR • V	VORN • U	NEVEN WEAR	
Oil leakage	FAIR · Attn	*1			COMMENT					
Power	FAIR · Attn				*1 油漏れあり	/(吸着	マットあり) O	IL LEAKING	(W/ABSORPTION	N MAT)
COOLING SYSTEM					*2 左シリンダーにじみあり LEFT CYLINDER: OIL OOZING					
Radiator	FAIR · Attn									
Oil Cooler	FAIR · Attn									
TRANSMIS										
T/M TYPE	PS · DD		No. OF GEARS -	- GEARS						
Transmission	FAIR · Attn									
Travel	FAIR · Attn									
Swing	FAIR · Attn									
Articulate	FAIR · Attn									
FOOT BRAKE	FAIR · Attn									
PARKING BRAKE	FAIR · Attn									
INTERIOR See Photos. 写真参照										
INTERIOR COND.	CLEAN	· FAIR ·	DIRTY							
Operator's Seat	FAIR · Attn									
Glasses	FAIR · Attn									
AirCon	A/C)·	H/C • H only	• C only •	None	RUST of BODY	(5: NONE	, 4: A LITTLE, 3:	MIDDLE, 2: MU	CH, 1: CORRODED)	4

This inspection information is for reference only at "the inspection date" by SOGO. NOT to guarantee the condition of the actual machine. この査定情報は『点検日時点』での参考資料であり、実際の機械の状態を保証するものではありません。