

INSPECTION SHEET 検品書
WHEEL LOADER タイヤショベル

INSPECTION DATE	2025/6/6	MAKE	CAT	MODEL	930M
SERIAL	CAT0930MPF5K00414			STAMP	CAT0930MPF5K00414
HR METER	12465 / 12475	HR	Odometer	28394	km
CAB/CNP	ROPS CAB / CAB / ROPS CNP / CNP / NONE			TIRE SIZE	20.5-25

ENGINE : MODEL	C7.1	S/N	J7A00996
Oil leakage	FAIR	Attn	
Blow-By	FAIR	Attn	A LITTLE · MIDDLE · SEVERE
Sound	FAIR	Attn	
Oil	FAIR	Attn	
Exhaust Color	FAIR	Attn	
US EPA	YES	NO	

OPERATION PUMP		
Sound	FAIR	Attn
Oil leakage	FAIR	Attn
Power	FAIR	Attn

COOLING SYSTEM		
Radiator	FAIR	Attn
Oil Cooler	FAIR	Attn

TRANSMISSION & TRAVEL		
T/M TYPE	PS · DD	
Transmission	FAIR · Attn	
Travel	FAIR · Attn	
FOOT BRAKE	FAIR · Attn	
PARKING BRAKE	FAIR · Attn	

INTERIOR	See Photos. 写真参照		
INTERIOR COND.	CLEAN	FAIR	DIRTY
Operator's Seat	FAIR	Attn	
Glasses	FAIR	Attn	
AirCon	A/C	H/C	H only · C only · None

FRONT & CYLINDERS		
Arm	FAIR · Attn	*1
Bell crank	FAIR · Attn	
Bucket	FAIR · Attn	
Articulate	FAIR · Attn	

UNDERCARRIAGE :	See Photos. 写真参照		
RUST (5: NONE, 4: A LITTLE, 3: MIDDLE, 2: MUCH, 1: CORRODED)	3		
TIRE WEAR	FAIR · WORN · UNEVEN WEAR		

COMMENT	
STEERING TYPE	WHEEL STEERING / COMMAND STEERING / LEVER STEERING

RIDE CONTROL	YES	NO
--------------	-----	----

ATTACHMENTS			
STD BKT	YES	OTHER	
BLADE	YES	NO	Piping for Tilt YES NO

COMMENT	
ロングアーム LONG ARM	
アドブルーメーター警告灯点灯あり	
WARNING LAMP FOR AdBlue: ON	
付属品:エアボスタイヤ4本 4 PIECES OF AIR BOSS TIRES AS SPARE	
*1 左シリンダー油漏れ小 LEFT CYLINDER: OIL LEAKING	

RUST of BODY (5: NONE, 4: A LITTLE, 3: MIDDLE, 2: MUCH, 1: CORRODED)	4
--	---

This inspection information is for reference only at "the inspection date" by SOGO. NOT to guarantee the condition of the actual machine.
この査定情報は『点検日時点』での参考資料であり、実際の機械の状態を保証するものではありません。