

INSPECTION SHEET 検品書
CRAWLER CRANE クローラクレーン

INSPECTION DATE	2025/5/26	MAKE	SUMITOMO	MODEL	SC500-2
SERIAL No.	PLATE : SC050-1151	STAMP	SC050-1151		
HR METER	9729	HR	SHOE	760FLAT	YEAR YR

ENGINE : MODEL		S/N	TA35273
Oil leakage	☒ FAIR · Attn		
Blow-By	☒ FAIR · Attn	A LITTLE · MIDDLE · ☒ SEVERE	
Sound	☒ FAIR · Attn		
Oil	☒ FAIR · Attn		
Exhaust Color	☒ FAIR · Attn		
OPERATION PUMP			
Sound	☒ FAIR · Attn		
Oil leakage	☒ FAIR · Attn		
Power	☒ FAIR · Attn		
COOLING SYSTEM			
Radiator	☒ FAIR · Attn		
Oil Cooler	☒ FAIR · Attn		
OPERATING SYSTEM			
Computer	☒ OK · NG		
Swing	☒ FAIR · Attn		
Travel	☒ FAIR · Attn		
BOOM			
MAIN BOOM	TOP, BOTTOM, 6m × 5, 3m × 1		
BOOM TOTAL	43m		
TOP SHEAVE	☒ YES · NO		
JIB			
TOWER			

INTERIOR		See Photos. 写真参照	
INTERIOR COND.	CLEAN · ☒ FAIR · DIRTY		
Operator's Seat	☒ FAIR · Attn	破れあり CUTS	
Glasses	☒ FAIR · Attn		
AirCon	☒ A/C · H/C · H only · C only · None		
UNDERCARRIAGE : See Photos. 写真参照			
RUST (5: NONE, 4: A LITTLE, 3: MIDDLE, 2: MUCH, 1: CORRODED)			3
COMMENT			
左右シューたるみあり TRACK LINKS: WORN			
WEIGHT	2		
HOOK	50t, 35t, 15t, BALL		
LIFTER	YES · ☒ NO		
COMMENT			
@NARITA YARD			
BOOM: TOP, BOTTOM, 6m × 1			
@SAKURA YARD			
BOOM: 6m × 4, 3m × 1			
HOOK: 35t, 15t, BALL			
RUST of BODY (5: NONE, 4: A LITTLE, 3: MIDDLE, 2: MUCH, 1: CORRODED)			2

This inspection information is for reference only at "the inspection date" by SOGO. NOT to guarantee the condition of the actual machine.
この査定情報は『点検日時点』での参考資料であり、実際の機械の状態を保証するものではありません。