

INSPECTION SHEET 検品書
LIFTING PLATFORM 高所作業車

INSPECTION DATE	2025/5/9	MAKE	AICHI	MODEL	SJ16A
SERIAL No.	PLATE : 684986			STAMP : NOT FOUND	
HR METER	7178	HR	Odometer	229041	km
YEAR	YR				
CHASSIS	MODEL KK-FE83ECY			No. 500763 / 国-211243	
SHOE	-			TIRE SIZE	225/80R17.5
MAX HIGHT	16.0			m	MAX WEIGHT 200 kg

ENGINE : MODEL S/N	
Oil leakage	<input checked="" type="radio"/> FAIR • Attn
Blow-By	<input checked="" type="radio"/> FAIR • Attn A LITTLE • MIDDLE • SEVERE
Sound	<input checked="" type="radio"/> FAIR • Attn
Oil	<input checked="" type="radio"/> FAIR • Attn
Exhaust Color	<input checked="" type="radio"/> FAIR • Attn
US EPA	YES <input checked="" type="radio"/> NO
OPERATION PUMP	
Sound	<input checked="" type="radio"/> FAIR • Attn
Oil leakage	<input checked="" type="radio"/> FAIR • Attn
Power	<input checked="" type="radio"/> FAIR • Attn
COOLING SYSTEM	
Radiator	<input checked="" type="radio"/> FAIR • Attn
Oil Cooler	<input checked="" type="radio"/> FAIR • Attn
TRANSMISSION & TRAVEL	
T/M TYPE	AT <input checked="" type="radio"/> MT *1 No. OF GEARS 6 GEARS
Transmission	<input checked="" type="radio"/> FAIR • Attn
4WD	4WD <input checked="" type="radio"/> 2WD
Travel	<input checked="" type="radio"/> FAIR • Attn
Swing	<input checked="" type="radio"/> FAIR • Attn
FOOT BRAKE	<input checked="" type="radio"/> FAIR • Attn
PARKING BRAKE	<input checked="" type="radio"/> FAIR • Attn
BOOM	
No. of Section	3 SECTIONS
DERRICKING CYL.	<input checked="" type="radio"/> FAIR • Attn
EXTENSION CYL.	<input checked="" type="radio"/> FAIR • Attn

INTERIOR See Photos. 写真参照	
INTERIOR COND.	<input checked="" type="radio"/> CLEAN • FAIR • DIRTY
Operator's Seat	<input checked="" type="radio"/> FAIR • Attn
Glasses	<input checked="" type="radio"/> FAIR • Attn
AirCon	<input checked="" type="radio"/> A/C • H/C • H only • C only • None
UNDERCARRIAGE : See Photos. 写真参照	
RUST (5: NONE, 4: A LITTLE, 3: MIDDLE, 2: MUCH, 1: CORRODED)	2
TIRE WEAR	<input checked="" type="radio"/> FAIR • WORN • UNEVEN WEAR
COMMENT	
OUTRIGGERS X • <input checked="" type="radio"/> H OUTRIGGERS COND. <input checked="" type="radio"/> FAIR • Attn	
COMMENT	
E/G暖まらないと作業側で再スタートしにくい(セルは回るが掛かりにくい) HARD TO RESTART THE ENGINE EVEN STARTER MOTOR IS RUNNING (ENGINE: NEED TO WARM) スペアタイヤあり W/SPARE TIRE *1 5速不良 5th GEAR: MALFUNCTION	
RUST of BODY (5: NONE, 4: A LITTLE, 3: MIDDLE, 2: MUCH, 1: CORRODED)	
3	

This inspection information is for reference only at "the inspection date" by SOGO. NOT to guarantee the condition of the actual machine.
 この査定情報は『点検日時点』での参考資料であり、実際の機械の状態を保証するものではありません。