

INSPECTION SHEET 検品書
EXCAVATOR バックホー

INSPECTION DATE	2025/4/17	MAKE	HITACHI	MODEL	EX60G
SERIAL	10F-1602		STAMP	10F-1602	
HR METER	9026	HR	YEAR	1991	YR
CAB/CNP	ROPS CAB / CAB / ROPS CNP / CNP / NONE		SHOE	600G	

ENGINE : MODEL		S/N
Oil leakage	FAIR · Attn	
Blow-By	FAIR · Attn	A LITTLE · MIDDLE · SEVERE
Sound	FAIR · Attn	
Oil	FAIR · Attn	
Exhaust Color	FAIR · Attn	
US EPA	YES · NO	
MAIN PUMP		
Sound	FAIR · Attn	
Oil leakage	FAIR · Attn	
Power	FAIR · Attn	
COOLING SYSTEM		
Radiator	FAIR · Attn	
Oil Cooler	FAIR · Attn	
OPERATING SYSTEM		
Swing	FAIR · Attn	ガタあり SWING: LOOSE
Travel	FAIR · Attn	
INTERIOR See Photos. 写真参照		
INTERIOR COND.	CLEAN · FAIR · DIRTY	
Operator's Seat	FAIR · Attn	破れ大 A LITTLE DAMAGED
Glasses	FAIR · Attn	*1
AirCon	A/C · H/C · H only · C only · None	
BOOM / ARM / BKT		
Boom	FAIR · Attn	
Boom Cylinder	FAIR · Attn	
Arm	FAIR · Attn	ガタあり LOOSE
Arm Cylinder	FAIR · Attn	
BKT	FAIR · Attn	ガタ、溶接あり LOOSE, WELDED
BKT Cylinder	FAIR · Attn	

UNDERCARRIAGE : See Photos. 写真参照	
RUST (5: NONE, 4: A LITTLE, 3: MIDDLE, 2: MUCH, 1: CORRODED)	3
COMMENT	
左右シューたるみあり TRACK LINKS: WORN	
シュープレートの取付ボルト1ヶ所欠	
SOME BOLT FOR SHOE PLATES: MISSING	
BKT	STD (<u>SLOPE</u>) NARROW / SKELETON / OTHER ()
Lever	(<u>LONG</u>) ▪ WRIST
Multi	MULTI ▪ 2 (<u>NO</u>)
ARM-CRANE	YES ▪ (<u>NO</u>)
BLADE	YES ▪ (<u>NO</u>)
OFFSET	YES ▪ (<u>NO</u>)
OFFSET Cylinder	FAIR ▪ Attn
Piping	YES ▪ (<u>NO</u>) Breaker only ▪ Multi
COMMENT	
燃料メーター、水温計不良	
FUEL GAUGE & WATER TEMPERATURE GAUGE: MALFUNCTION	
*1 右窓外枠テープあり	
*1 OUTSIDE OF RIGHT DOOR GLASS FRAME: COVERED WITH ADHESIVE TAPES	
RUST of BODY (5: NONE, 4: A LITTLE, 3: MIDDLE, 2: MUCH, 1: CORRODED)	
1	

This inspection information is for reference only at "the inspection date" by SOGO. NOT to guarantee the condition of the actual machine.

この査定情報は『点検日時点』での参考資料であり、実際の機械の状態を保証するものではありません。