

INSPECTION SHEET 検品書
EXCAVATOR バックホー

INSPECTION DATE	2025/5/20	MAKE	KOMATSU	MODEL	PC230LC-8N1
SERIAL	80425		STAMP	KMTPC198J02080425	
HR METER	6082	HR	YEAR	2010	YR
CAB/CNP	ROPS CAB / CAB / ROPS CNP / CNP / NONE		SHOE	800G	

ENGINE :		MODEL	6D107E-1	S/N	26552872
Oil leakage	FAIR	Attn			
Blow-By	FAIR	Attn	A LITTLE	MIDDLE	SEVERE
Sound	FAIR	Attn			
Oil	FAIR	Attn			
Exhaust Color	FAIR	Attn			
US EPA	YES	NO			
MAIN PUMP					
Sound	FAIR	Attn			
Oil leakage	FAIR	Attn			
Power	FAIR	Attn			
COOLING SYSTEM					
Radiator	FAIR	Attn			
Oil Cooler	FAIR	Attn			
OPERATING SYSTEM					
Swing	FAIR	Attn	ガタあり SWING: LOOSE		
Travel	FAIR	Attn			
INTERIOR See Photos. 写真参照					
INTERIOR COND.	CLEAN	FAIR	DIRTY		
Operator's Seat	FAIR	Attn			
Glasses	FAIR	Attn			
AirCon	A/C	H/C	H only	C only	None
BOOM / ARM / BKT					
Boom	FAIR	Attn			
Boom Cylinder	FAIR	Attn	左側油漏れ小 LEFT CYLINDER: OIL LEAKING		
Arm	FAIR	Attn	ガタあり LOOSE		
Arm Cylinder	FAIR	Attn			
BKT	FAIR	Attn	ガタ、補修あり LOOSE, REPAIRED		
BKT Cylinder	FAIR	Attn			

UNDERCARRIAGE : See Photos. 写真参照	
RUST (5: NONE, 4: A LITTLE, 3: MIDDLE, 2: MUCH, 1: CORRODED)	3
COMMENT 左右トラックローラーガタあり SOME TRACK ROLLERS: LOOSE	
BKT	(STD / SLOPE / NARROW / SKELETON / OTHER()
Lever	LONG ▪ (WRIST)
Multi	MULTI ▪ 2 ▪ (NO)
ARM-CRANE	YES ▪ (NO)
BLADE	YES ▪ (NO)
OFFSET	YES ▪ (NO)
OFFSET Cylinder	FAIR ▪ Attn
Piping	YES ▪ (NO) Breaker only ▪ Multi
COMMENT 水位チェックランプ点灯、ブザー音あり(水量OK) WARNING LAMP FOR COOLANT LEVEL & WARNING SOUNDS: ON (COOLANT LEVEL: OK) バックカメラ映らない BACK MONITOR: NOT DISPLAYING	
RUST of BODY (5: NONE, 4: A LITTLE, 3: MIDDLE, 2: MUCH, 1: CORRODED)	
3	

This inspection information is for reference only at "the inspection date" by SOGO. NOT to guarantee the condition of the actual machine.

この査定情報は『点検日時点』での参考資料であり、実際の機械の状態を保証するものではありません。