

INSPECTION SHEET 検品書
WHEEL LOADER タイヤショベル

INSPECTION DATE	2025/5/21	MAKE	FURUKAWA	MODEL	FL50-I		
SERIAL	1769		STAMP	F18-1769			
HR METER	7096	HR	Odometer	—	km	YEAR	YR
CAB/CNP	ROPS CAB / CAB / ROPS CNP / CNP / NONE		TIRE SIZE	15.5/70-18			

ENGINE : MODEL		S/N
Oil leakage	FAIR · Attn	油汚れあり OIL STAINS
Blow-By	FAIR · Attn	A LITTLE · MIDDLE · SEVERE
Sound	FAIR · Attn	
Oil	FAIR · Attn	
Exhaust Color	FAIR · Attn	
US EPA	YES · NO	

OPERATION PUMP		
Sound	FAIR	Attn
Oil leakage	FAIR	Attn
Power	FAIR	Attn

COOLING SYSTEM		
Radiator	FAIR	Attn
Oil Cooler	FAIR	Attn

TRANSMISSION & TRAVEL		
T/M TYPE	PS · DD	
Transmission	FAIR · Attn	
Travel	FAIR · Attn	
FOOT BRAKE	FAIR · Attn	
PARKING BRAKE	FAIR · Attn	

INTERIOR		See Photos. 写真参照	
INTERIOR COND.	CLEAN ・ FAIR ・ DIRTY		
Operator's Seat	FAIR ・ Attn	破れあり HUGE CUTS	
Glasses	FAIR ・ Attn	左右割れあり SIDE GLASSES: CRACKED	
AirCon	A/C ・ H/C ・ H only ・ C only ・ None		

FRONT & CYLINDERS		
Arm	FAIR ・ Attn	左右シリンダー油漏れあり CYLINDERS: OIL LEAKING
Bell crank	FAIR ・ Attn	
Bucket	FAIR ・ Attn	シリンダー油漏れあり CYLINDER: OIL LEAKING
Articulate	FAIR ・ Attn	


UNDERCARRIAGE : See Photos. 写真参照	
RUST (5: NONE, 4: A LITTLE, 3: MIDDLE, 2: MUCH, 1: CORRODED)	2
TIRE WEAR (FAIR • WORN • UNEVEN WEAR)	

COMMENT	

STEERING TYPE	WHEEL STEERING / COMMAND STEERING / LEVER STEERING	
RIDE CONTROL	YES	NO

ATTACHMENTS				
STD BKT	☒ YES	☐ OTHER		
BLADE	☒ YES	☐ NO	Piping for Tilt	☒ YES ☐ NO

COMMENT
燃料フィルター漏れ小 FUEL FILTER: FUEL LEAKING
バケット操作レバーガタあり BUCKET OPERATION LEVER: LOOSE
リリーフ掛けるとエンストする
ENGINE STALLING WITH ENGINE LOAD INCREASING
ヒーター風出ない HEATER: A/C: NOT BLOWING AIR

		2
RUST of BODY (5: NONE, 4: A LITTLE, 3: MIDDLE, 2: MUCH, 1: CORRODED)		

This inspection information is for reference only at "the inspection date" by SOGO. NOT to guarantee the condition of the actual machine.
この査定情報は『点検日時点』での参考資料であり、実際の機械の状態を保証するものではありません。