

INSPECTION SHEET 検品書
ROUGH TERRAIN CRANE ラフタークレーン

INSPECTION DATE	2025/6/6	MAKE	TADANO	MODEL	TR-350M-2
SERIAL No.	PLATE : 505753		STAMP : TR351-??66 SOME LETTERS: UNREADABLE		
HR METER	5948	HR	Odometer	44875	km
TIRE SIZE	16.00R25		YEAR	YR	

ENGINE : MODEL		S/N
Oil leakage	FAIR • Attn	
Blow-By	FAIR • Attn	A LITTLE • MIDDLE • SEVERE
Sound	FAIR • Attn	
Oil	FAIR • Attn	
Exhaust Color	FAIR • Attn	

OPERATION PUMP		
Sound	FAIR	Attn
Oil leakage	FAIR	Attn
Power	FAIR	Attn

COOLING SYSTEM		
Radiator	FAIR	Attn
Oil Cooler	FAIR	Attn

OPERATING SYSTEM		
Computer	OK	NG
Swing	FAIR	Attn
Travel	FAIR	Attn *1

TRANSMISSION		
Transmission	FAIR	Ⓐ Attn 変速しない UNABLE TO SHIFT GEARS
No. OF GEARS	3	GEARS
4WD	Ⓐ 4WD	・ 6WD

INTERIOR		See Photos. 写真参照
INTERIOR COND.	CLEAN ・ FAIR ・ DIRTY	
Operator's Seat	FAIR ・ Attn	破れあり CUT
Glasses	FAIR ・ Attn	
AirCon	A/C ・ H/C ・ H only ・ C only ・ None	

COMMENT	

BOOM		
No. of Section	5	SECTIONS
CRACK/ENFORCEMENT	☐ FAIR ▪ Attn	
DERRICKING CYL.	☐ FAIR ▪ Attn	
EXTENSION CYL.	☐ FAIR ▪ Attn	
JIB	☐ YES ▪ NO	
JIB TYPE	STD ▪ ☐ PWR	
MAIN & SUB WIRE	☐ YES ▪ NO	
HOOK	20t, BALL	

UNDERCARRIAGE : See Photos. 写真参照	
RUST (5: NONE, 4: A LITTLE, 3: MIDDLE, 2: MUCH, 1: CORRODED)	1

TIRE WEAR	FAIR • WORN • <u>UNEVEN WEAR</u>
-----------	----------------------------------

COMMENT
左Fタイヤ横ひび割れあり FRONT LEFT TIRE SIDEWALL: CRACKED

OUTRIGGERS		
OUTRIGGERS	(X)	▪ H
OUTRIGGERS COND.	(FAIR)	▪ Attn

Oil leakage (JACK CYL.)	FRONT	L ▪ R	REAR	L ▪ R
Oil leakage (SLIDE CYL.)	FRONT	L ▪ R	REAR	L ▪ R

COMMENT	
*1 公道自走不可 UNABLE TO RUN ON PUBLIC ROADS	
RUST of BODY (5: NONE, 4: A LITTLE, 3: MIDDLE, 2: MUCH, 1: CORRODED)	1

This inspection information is for reference only at "the inspection date" by SOGO. NOT to guarantee the condition of the actual machine.

この査定情報は『点検日時点』での参考資料であり、実際の機械の状態を保証するものではありません。