

INSPECTION SHEET 検品書
EXCAVATOR バックホー

INSPECTION DATE	2025/5/27	MAKE	HITACHI	MODEL	EX300-5
SERIAL	1H1P022197			STAMP	1H1P022197
HR METER	39553	HR	YEAR	YR	
CAB/CNP	ROPS CAB / CAB / ROPS CNP / CNP / NONE			SHOE	600G

ENGINE : MODEL		S/N
Oil leakage	FAIR · Attn	
Blow-By	FAIR · Attn	A LITTLE · MIDDLE · SEVERE
Sound	FAIR · Attn	
Oil	FAIR · Attn	
Exhaust Color	FAIR · Attn	
US EPA	YES · NO	
MAIN PUMP		
Sound	FAIR · Attn	
Oil leakage	FAIR · Attn	油漏れあり OIL LEAKING
Power	FAIR · Attn	
COOLING SYSTEM		
Radiator	FAIR · Attn	
Oil Cooler	FAIR · Attn	
OPERATING SYSTEM		
Swing	FAIR · Attn	ガタあり SWING: LOOSE
Travel	FAIR · Attn	HI/LO切替え不良 HI/LO SWITCH: MALFUNCTION
INTERIOR See Photos. 写真参照		
INTERIOR COND.	CLEAN · FAIR · DIRTY	
Operator's Seat	FAIR · Attn	穴あり HOLE
Glasses	FAIR · Attn	
AirCon	A/C · H/C · H only · C only · None	
BOOM / ARM / BKT		
Boom	FAIR · Attn	
Boom Cylinder	FAIR · Attn	
Arm	FAIR · Attn	
Arm Cylinder	FAIR · Attn	
BKT	FAIR · Attn	
BKT Cylinder	FAIR · Attn	傷あり SCRATCHED

UNDERCARRIAGE : See Photos. 写真参照	
RUST (5: NONE, 4: A LITTLE, 3: MIDDLE, 2: MUCH, 1: CORRODED)	2
COMMENT	
左右ピンブッシュ割れあり SOME PIN BUSHES: BROKEN	
左側キャリアローラー欠、軸摩耗、トラックローラーガタあり	
LEFT CARRIER ROLLERS: MISSING, LEFT CARRIER ROLLER SHAFTS: MUCH WORN,	
SOME LEFT TRACK ROLLERS: LOOSE	
BKT	STD / SLOPE / NARROW / SKELETON / OTHER ()
Lever	LONG · WRIST
Multi	MULTI · 2 · NO
ARM-CRANE	YES · NO
BLADE	YES · NO
OFFSET	YES · NO
OFFSET Cylinder	FAIR · Attn
Piping	YES · NO Breaker only · Multi
COMMENT	
右側キャリアローラー曲がり、偏摩耗、トラックローラーガタあり	
RIGHT CARRIER ROLLERS: BENT, UNEVEN WEARING,	
SOME RIGHT TRACK ROLLERS: LOOSE	
ハイCAB HIGH CAB	
CABドア閉まらない DOOR: UNABLE TO SHUT	
左サイドカバー閉まらない LEFT SIDE COVER: UNABLE TO SHUT	
マグネット用電源立ち上がらない	
MAGNET POWER SUPPLY: UNABLE TO TURN ON	
A/C冷えない A/C: MALFUNCTION	
コントロールバルブ下周り油漏れあり	
BOTTOM OF CONTROL VALVE: OIL LEAKING	
アタッチメントなし WITHOUT ATTACHMENT	
RUST of BODY (5: NONE, 4: A LITTLE, 3: MIDDLE, 2: MUCH, 1: CORRODED)	2

This inspection information is for reference only at "the inspection date" by SOGO. NOT to guarantee the condition of the actual machine.

この査定情報は『点検日時点』での参考資料であり、実際の機械の状態を保証するものではありません。