

INSPECTION SHEET 検品書
ASPHALT FINISHER アスファルトフィニッシャー

INSPECTION DATE	2025/5/15	MAKE	SUMITOMO	MODEL	HA45W-7
SERIAL	HANF45W3L00050847			STAMP	HANF45W3L00050847
HR METER	4434	HR	YEAR	YR	
SHOE		TIRE (REAR)	365/80R20	MAX PAVING WIDTH	4600 mm

ENGINE : MODEL S/N <table border="1" style="width: 100%; border-collapse: collapse;"> <tr> <td style="width: 15%;">Oil leakage</td> <td style="width: 10%; text-align: center;">FAIR</td> <td style="width: 10%;">Attn</td> <td style="width: 65%;"></td> </tr> <tr> <td>Blow-By</td> <td style="text-align: center;">FAIR</td> <td>Attn</td> <td>A LITTLE ・ MIDDLE ・ SEVERE</td> </tr> <tr> <td>Sound</td> <td style="text-align: center;">FAIR</td> <td>Attn</td> <td></td> </tr> <tr> <td>Oil</td> <td style="text-align: center;">FAIR</td> <td>Attn</td> <td></td> </tr> <tr> <td>Exhaust Color</td> <td style="text-align: center;">FAIR</td> <td>Attn</td> <td></td> </tr> <tr> <td>US EPA</td> <td>YES</td> <td style="text-align: center;">NO</td> <td></td> </tr> </table> OPERATION PUMP <table border="1" style="width: 100%; border-collapse: collapse;"> <tr> <td style="width: 15%;">Sound</td> <td style="width: 10%; text-align: center;">FAIR</td> <td style="width: 10%;">Attn</td> <td style="width: 65%;"></td> </tr> <tr> <td>Oil leakage</td> <td style="text-align: center;">FAIR</td> <td>Attn</td> <td></td> </tr> <tr> <td>Power</td> <td style="text-align: center;">FAIR</td> <td>Attn</td> <td></td> </tr> </table> COOLING SYSTEM <table border="1" style="width: 100%; border-collapse: collapse;"> <tr> <td style="width: 15%;">Radiator</td> <td style="width: 10%; text-align: center;">FAIR</td> <td style="width: 10%;">Attn</td> <td style="width: 65%;"></td> </tr> <tr> <td>Oil Cooler</td> <td style="text-align: center;">FAIR</td> <td>Attn</td> <td></td> </tr> </table> OPERATING SYSTEM <table border="1" style="width: 100%; border-collapse: collapse;"> <tr> <td style="width: 15%;">TRAVEL</td> <td style="width: 10%; text-align: center;">FAIR</td> <td style="width: 10%;">Attn</td> <td style="width: 65%;"></td> </tr> <tr> <td>SCREED(R)</td> <td style="text-align: center;">FAIR</td> <td>Attn</td> <td></td> </tr> <tr> <td>SCREED(L)</td> <td style="text-align: center;">FAIR</td> <td>Attn</td> <td></td> </tr> <tr> <td>VIBRATION</td> <td style="text-align: center;">FAIR</td> <td>Attn</td> <td></td> </tr> <tr> <td>TAMPER</td> <td style="text-align: center;">FAIR</td> <td>Attn</td> <td></td> </tr> <tr> <td>SPREADER(R)</td> <td style="text-align: center;">FAIR</td> <td>Attn</td> <td></td> </tr> <tr> <td>SPREADER(L)</td> <td style="text-align: center;">FAIR</td> <td>Attn</td> <td></td> </tr> <tr> <td>HOPPER(R)</td> <td style="text-align: center;">FAIR</td> <td>Attn</td> <td></td> </tr> <tr> <td>HOPPER(L)</td> <td style="text-align: center;">FAIR</td> <td style="text-align: center;">Attn</td> <td>シリンダー油漏れ小 CYLINDER: OIL LEAKING</td> </tr> <tr> <td>FEEDER</td> <td style="text-align: center;">FAIR</td> <td>Attn</td> <td></td> </tr> </table>	Oil leakage	FAIR	Attn		Blow-By	FAIR	Attn	A LITTLE ・ MIDDLE ・ SEVERE	Sound	FAIR	Attn		Oil	FAIR	Attn		Exhaust Color	FAIR	Attn		US EPA	YES	NO		Sound	FAIR	Attn		Oil leakage	FAIR	Attn		Power	FAIR	Attn		Radiator	FAIR	Attn		Oil Cooler	FAIR	Attn		TRAVEL	FAIR	Attn		SCREED(R)	FAIR	Attn		SCREED(L)	FAIR	Attn		VIBRATION	FAIR	Attn		TAMPER	FAIR	Attn		SPREADER(R)	FAIR	Attn		SPREADER(L)	FAIR	Attn		HOPPER(R)	FAIR	Attn		HOPPER(L)	FAIR	Attn	シリンダー油漏れ小 CYLINDER: OIL LEAKING	FEEDER	FAIR	Attn		UNDERCARRIAGE : See Photos. 写真参照 <table border="1" style="width: 100%; border-collapse: collapse;"> <tr> <td style="width: 85%;">RUST (5: NONE, 4: A LITTLE, 3: MIDDLE, 2: MUCH, 1: CORRODED)</td> <td style="width: 15%; text-align: center;">2</td> </tr> <tr> <td>TIRE WEAR</td> <td style="text-align: center;">FAIR</td> </tr> </table> COMMENT SCREED WIDTH <table border="1" style="width: 100%; border-collapse: collapse;"> <tr> <td style="width: 40%;">MAIN SCREED</td> <td style="width: 20%; text-align: center;">2.2</td> <td style="width: 40%; text-align: right;">m</td> </tr> <tr> <td>WITH AUTO-WIDENER</td> <td style="text-align: center;">4.6</td> <td style="text-align: right;">m</td> </tr> <tr> <td>WITH EXTENSION</td> <td></td> <td style="text-align: right;">m</td> </tr> </table> <table border="1" style="width: 100%; border-collapse: collapse;"> <tr> <td style="width: 40%;">LEVEL SENSOR</td> <td style="width: 20%;">YES</td> <td style="width: 40%; text-align: center;">NO</td> </tr> </table> COMMENT 左側スクリードリフトシリンダーにじみあり LEFT SCREED LIFT CYLINDER: OIL Oozing シートガタ、損傷あり SEAT: LOOSE, A LITTLE DAMAGED	RUST (5: NONE, 4: A LITTLE, 3: MIDDLE, 2: MUCH, 1: CORRODED)	2	TIRE WEAR	FAIR	MAIN SCREED	2.2	m	WITH AUTO-WIDENER	4.6	m	WITH EXTENSION		m	LEVEL SENSOR	YES	NO
Oil leakage	FAIR	Attn																																																																																																			
Blow-By	FAIR	Attn	A LITTLE ・ MIDDLE ・ SEVERE																																																																																																		
Sound	FAIR	Attn																																																																																																			
Oil	FAIR	Attn																																																																																																			
Exhaust Color	FAIR	Attn																																																																																																			
US EPA	YES	NO																																																																																																			
Sound	FAIR	Attn																																																																																																			
Oil leakage	FAIR	Attn																																																																																																			
Power	FAIR	Attn																																																																																																			
Radiator	FAIR	Attn																																																																																																			
Oil Cooler	FAIR	Attn																																																																																																			
TRAVEL	FAIR	Attn																																																																																																			
SCREED(R)	FAIR	Attn																																																																																																			
SCREED(L)	FAIR	Attn																																																																																																			
VIBRATION	FAIR	Attn																																																																																																			
TAMPER	FAIR	Attn																																																																																																			
SPREADER(R)	FAIR	Attn																																																																																																			
SPREADER(L)	FAIR	Attn																																																																																																			
HOPPER(R)	FAIR	Attn																																																																																																			
HOPPER(L)	FAIR	Attn	シリンダー油漏れ小 CYLINDER: OIL LEAKING																																																																																																		
FEEDER	FAIR	Attn																																																																																																			
RUST (5: NONE, 4: A LITTLE, 3: MIDDLE, 2: MUCH, 1: CORRODED)	2																																																																																																				
TIRE WEAR	FAIR																																																																																																				
MAIN SCREED	2.2	m																																																																																																			
WITH AUTO-WIDENER	4.6	m																																																																																																			
WITH EXTENSION		m																																																																																																			
LEVEL SENSOR	YES	NO																																																																																																			
<table border="1" style="width: 100%; border-collapse: collapse;"> <tr> <td style="width: 85%;">RUST of BODY (5: NONE, 4: A LITTLE, 3: MIDDLE, 2: MUCH, 1: CORRODED)</td> <td style="width: 15%; text-align: center;">2</td> </tr> </table>				RUST of BODY (5: NONE, 4: A LITTLE, 3: MIDDLE, 2: MUCH, 1: CORRODED)	2																																																																																																
RUST of BODY (5: NONE, 4: A LITTLE, 3: MIDDLE, 2: MUCH, 1: CORRODED)	2																																																																																																				

This inspection information is for reference only at "the inspection date" by SOGO. NOT to guarantee the condition of the actual machine.
 この査定情報は『点検日時点』での参考資料であり、実際の機械の状態を保証するものではありません。