

INSPECTION SHEET 検品書
EXCAVATOR バックホー

INSPECTION DATE	2025/5/8	MAKE	KOBELCO	MODEL	SK45SR-6
SERIAL	PH08-10374		STAMP	PH08-10374	
HR METER	1003	HR	YEAR	YR	
CAB/CNP	ROPS CAB / CAB / <u>ROPS CNP</u> / CNP / NONE		SHOE	400G PADS	

ENGINE : MODEL		S/N
Oil leakage	FAIR · Attn	
Blow-By	FAIR · Attn	A LITTLE · MIDDLE · SEVERE
Sound	FAIR · Attn	
Oil	FAIR · Attn	
Exhaust Color	FAIR · Attn	
US EPA	YES · NO	
MAIN PUMP		
Sound	FAIR · Attn	
Oil leakage	FAIR · Attn	
Power	FAIR · Attn	
COOLING SYSTEM		
Radiator	FAIR · Attn	
Oil Cooler	FAIR · Attn	
OPERATING SYSTEM		
Swing	FAIR · Attn	ガタあり SWING: LOOSE
Travel	FAIR · Attn	
INTERIOR See Photos. 写真参照		
INTERIOR COND.	CLEAN · FAIR · DIRTY	
Operator's Seat	FAIR · Attn	
Glasses	FAIR · Attn	
AirCon	A/C · H/C · H only · C only · None	
BOOM / ARM / BKT		
Boom	FAIR · Attn	
Boom Cylinder	FAIR · Attn	
Arm	FAIR · Attn	
Arm Cylinder	FAIR · Attn	
BKT	FAIR · Attn	
BKT Cylinder	FAIR · Attn	

UNDERCARRIAGE :		See Photos.	写真参照
RUST (5: NONE, 4: A LITTLE, 3: MIDDLE, 2: MUCH, 1: CORRODED)			3
COMMENT			
BKT	(STD / SLOPE / NARROW / SKELETON / OTHER()		
Lever	LONG ▪ (WRIST)		
Multi	(MULTI) ▪ 2 ▪ NO		
ARM-CRANE	(YES) ▪ NO	*1	
BLADE	(YES) ▪ NO		
OFFSET	YES ▪ (NO)		
OFFSET Cylinder	FAIR ▪ Attn		
Piping	(YES) ▪ NO	Breaker only ▪ (Multi)	
COMMENT			
スイング部ガタあり SWING PART: LOOSE			
*1 アーム角度センサ異常表示あり			
*1 WARNING DISPLAY FOR ARM ANGLE SENSOR			
RUST of BODY (5: NONE, 4: A LITTLE, 3: MIDDLE, 2: MUCH, 1: CORRODED)			4

This inspection information is for reference only at "the inspection date" by SOGO. NOT to guarantee the condition of the actual machine.

この査定情報は『点検日時点』での参考資料であり、実際の機械の状態を保証するものではありません。