

INSPECTION SHEET 検品書
EXCAVATOR バックホー

INSPECTION DATE	2025/6/4	MAKE	KUBOTA	MODEL	RX-503S
SERIAL	30734		STAMP	30734	
HR METER	5532	HR	YEAR	YR	
CAB/CNP	ROPS CAB / CAB / ROPS CNP / CNP / NONE		SHOE	400R	

ENGINE :		MODEL	V2203	S/N	06Q0260
Oil leakage	(FAIR)	Attn			
Blow-By	(FAIR)	Attn	A LITTLE · MIDDLE · SEVERE		
Sound	(FAIR)	Attn			
Oil	(FAIR)	Attn			
Exhaust Color	(FAIR)	Attn			
US EPA	YES	(NO)			
MAIN PUMP					
Sound	(FAIR)	Attn			
Oil leakage	(FAIR)	Attn			
Power	(FAIR)	Attn			
COOLING SYSTEM					
Radiator	(FAIR)	Attn			
Oil Cooler	(FAIR)	Attn			
OPERATING SYSTEM					
Swing	(FAIR)	Attn			
Travel	(FAIR)	Attn			
INTERIOR See Photos. 写真参照					
INTERIOR COND.	CLEAN	·	(FAIR)	·	DIRTY
Operator's Seat	(FAIR)	Attn			
Glasses	FAIR	· Attn			
AirCon	A/C	· H/C	· H only	· C only	· (None)
BOOM / ARM / BKT					
Boom	(FAIR)	Attn			
Boom Cylinder	(FAIR)	Attn			
Arm	(FAIR)	Attn			
Arm Cylinder	(FAIR)	Attn			
BKT	FAIR	· (Attn)	ガタ小 LOOSE		
BKT Cylinder	(FAIR)	Attn			

UNDERCARRIAGE :		See Photos. 写真参照	
RUST (5: NONE, 4: A LITTLE, 3: MIDDLE, 2: MUCH, 1: CORRODED)		3	
COMMENT			
BKT	(STD)	SLOPE / NARROW / SKELETON / OTHER()	
Lever	LONG	· (WRIST)	
Multi	MULTI	· 2	· (NO)
ARM-CRANE	YES	· (NO)	
BLADE	(YES)	· NO	変形小 A LITTLE DEFORMED
OFFSET	(YES)	· NO	
OFFSET Cylinder	(FAIR)	· Attn	
Piping	YES	· (NO)	Breaker only · Multi
COMMENT			
RUST of BODY (5: NONE, 4: A LITTLE, 3: MIDDLE, 2: MUCH, 1: CORRODED)		3	

This inspection information is for reference only at "the inspection date" by SOGO. NOT to guarantee the condition of the actual machine.

この査定情報は『点検日時点』での参考資料であり、実際の機械の状態を保証するものではありません。