

INSPECTION SHEET 検品書
CARRY DUMP キャリーダンプ

INSPECTION DATE	2025/5/9	MAKE	IHI	MODEL	IC100-2
SERIAL	CB001044			STAMP	CB001044
HR METER	4429	HR	Odometer	km	YEAR
CAB/CNP	ROPS CAB / CAB / ROPS CNP / CNP / NONE			SHOE	750R
				TIRE	

ENGINE : MODEL						6HK1		S/N	
Oil leakage		FAIR		Attn					
Blow-By		FAIR		Attn		A LITTLE · MIDDLE · SEVERE			
Sound		FAIR		Attn					
Oil		FAIR		Attn					
Exhaust Color		FAIR		Attn					
US EPA		YES		NO					
OPERATION PUMP									
Sound		FAIR		Attn					
Oil leakage		FAIR		Attn					
Power		FAIR		Attn					
COOLING SYSTEM									
Radiator		FAIR		Attn					
Oil Cooler		FAIR		Attn					
TRANSMISSION & TRAVEL									
T/M TYPE		PS		DD				No. OF GEARS	2 GEAR(S)
Transmission		FAIR		Attn					
Travel		FAIR		Attn		*1			
Swing		FAIR		Attn					
Articulate		FAIR		Attn					
FOOT BRAKE		FAIR		Attn					
PARKING BRAKE		FAIR		Attn					
INTERIOR See Photos. 写真参照									
INTERIOR COND.		CLEAN ·		FAIR		DIRTY			
Operator's Seat		FAIR		Attn					
Glasses		FAIR		Attn					
AirCon		A/C		H/C · H only · C only · None					

MAIN FRAME								
MAIN FLAME		FAIR		Attn				
VESSEL								
VESSEL		FAIR		Attn				
REAR GATE TYPE		NORMAL		L-GATE (FLAT)				
REAR GATE		FAIR		Attn				
UNDERCARRIAGE: See Photos. 写真参照								
RUST (5: NONE, 4: A LITTLE, 3: MIDDLE, 2: MUCH, 1: CORRODED)						3		
TIRE WEAR		FAIR · WORN · UNEVEN WEAR						
COMMENT								
ラジエータフード鍵挿さらない、開閉不可								
KEY CYLINDER OF RADIATOR HOOD:								
UNABLE TO INSERT THE KEY, UNABLE TO OPEN or CLOSE								
*1 直進時少しずつ右に曲がる								
*1 A LITTLE TOTTERING TO RIGHT DURING TRAVELING FORWARD								
RUST of BODY (5: NONE, 4: A LITTLE, 3: MIDDLE, 2: MUCH, 1: CORRODED)						3		

This inspection information is for reference only at "the inspection date" by SOGO. NOT to guarantee the condition of the actual machine.
この査定情報は『点検日時点』での参考資料であり、実際の機械の状態を保証するものではありません。