INSPECTION SHEET 検品書 CARRY DUMP キャリーダンプ

INSPECTION DATE		2025/6/6			MAKE		IHI			DEL	IC100-2		
SERIAL	CB001115					-	STAMP	STAMP			CB001115		
HR METER	4370 HR Odome				eter			k	m \	/EAR			YR
CAB/CNP	ROPS CA	B CAE	ROP	S CNP	/ CNP /	/ NONE	SHOE		740F	?	TIRE		
ENGINE :	MAIN FRAME												
Oil leakage	FAIR · Attn						MAIN FLAME FAIR - Attn						
Blow-By	FAIR · Attn A LITTLE · MIDDLE · SEVERE						VESSEL						
Sound	FAIR · Attn						VESSE	EL (FAIR	■ Attn			
Oil	FAIR · Attn						REAR GATE	TYPE	NC	DRMAL	. • L-	GATE (FLAT)	
Exhaust Color	FAIR · Attn						REAR GA	ATE	FAIR	Attn			
US EPA	YES)· NO						UNDERCARRIAGE: See Photos. 写真参照						
OPERATION PUMP							RUST (5: NONE, 4: A LITTLE, 3: MIDDLE, 2: MUCH, 1: CORRODED) 4						
Sound	FAIR · Attn						TIRE WE	AR	FA	IR • W	ORN • UI	NEVEN WEAR	
Oil leakage	FAIR · Attn						COMMENT	-					
Power	FAIR · Attn												
COOLING SYSTEM													
Radiator	FAIR · Attn												
Oil Cooler	FAIR · Attn												
TRANSMIS													
T/M TYPE	PS) · DD			No. OF GI	EARS 2	GEARS							
Transmission	FAIR · Attn			, and the second									
Travel	FAIR · Attn												
Swing	FAIR · Attn												
Articulate	FAIR · Attn												
FOOT BRAKE	FAIR · Attn												
PARKING BRAKE	FAIR · Attn												
INTERIOR See Photos. 写真参照													
INTERIOR COND.	CLEAN	· (F/	AIR •	DIRT	Υ								
Operator's Seat	FAIR · Attn												
Glasses	FAIR · Attn												
AirCon	A/C) ·	H/C •	H only	• C o	nly •	None	RUST of BODY	(5: NONE,	4: A LI	TTLE, 3: M	IIDDLE, 2: MU	CH, 1: CORRODED)	2

This inspection information is for reference only at "the inspection date" by SOGO. NOT to guarantee the condition of the actual machine. この査定情報は『点検日時点』での参考資料であり、実際の機械の状態を保証するものではありません。