

INSPECTION SHEET 検品書
WHEEL LOADER タイヤショベル

INSPECTION DATE	2025/5/13	MAKE	HITACHI	MODEL	LX70-5		
SERIAL	41WP005263			STAMP	L705-5263		
HR METER	8454	HR	Odometer	-	km	YEAR	YR
CAB/CNP	ROPS CAB / CAB / ROPS CNP / CNP / NONE			TIRE SIZE	16.9-24 12PR		

ENGINE : MODEL		S/N
Oil leakage	FAIR • ☒ Attn	*1
Blow-By	FAIR • Attn	A LITTLE • MIDDLE • SEVERE
Sound	FAIR • Attn	
Oil	FAIR • Attn	
Exhaust Color	FAIR • Attn	
US EPA	YES • ☒ NO	
OPERATION PUMP		
Sound	FAIR • Attn	
Oil leakage	FAIR • Attn	
Power	FAIR • Attn	
COOLING SYSTEM		
Radiator	FAIR • Attn	
Oil Cooler	FAIR • Attn	
TRANSMISSION & TRAVEL		
T/M TYPE	PS • ☒ DD	
Transmission	FAIR • Attn	
Travel	FAIR • Attn	
FOOT BRAKE	FAIR • Attn	
PARKING BRAKE	FAIR • Attn	
INTERIOR See Photos. 写真参照		
INTERIOR COND.	CLEAN • ☒ FAIR • DIRTY	
Operator's Seat	FAIR • Attn	
Glasses	FAIR • ☒ Attn	*2
AirCon	A/C • ☒ H/C • H only • C only • None	
FRONT & CYLINDERS		
Arm	FAIR • ☒ Attn	左右シリンダーにじみあり CYLINDERS: OIL OOZING
Bell crank	FAIR • Attn	
Bucket	FAIR • Attn	
Articulate	FAIR • Attn	

UNDERCARRIAGE : See Photos. 写真参照	
RUST (5: NONE, 4: A LITTLE, 3: MIDDLE, 2: MUCH, 1: CORRODED)	3
TIRE WEAR	☒ FAIR • WORN • UNEVEN WEAR
COMMENT	
下周り油漏れあり(吸着マットあり)	
BOTTOM: OIL LEAKING (W/ABSORPTION MAT)	
STEERING TYPE ☒ WHEEL STEERING / ☐ COMMAND STEERING / ☐ LEVER STEERING	
RIDE CONTROL	YES • ☒ NO
ATTACHMENTS	
STD BKT	☒ YES • OTHER
BLADE	YES • ☒ NO Piping for Tilt YES • ☒ NO
COMMENT	
機体外装リペイントあり REPAINTED	
右ドア開かない RIGHT DOOR: UNABLE TO OPEN	
*1 ヘッドカバー油にじみあり HEAD COVER: OIL OOZING	
*2 右ドア窓閉まらない、バンド固定あり	
*2 RIGHT DOOR GLASS: UNABLE TO SHUT (FIXING WITH STRINGS)	
RUST of BODY (5: NONE, 4: A LITTLE, 3: MIDDLE, 2: MUCH, 1: CORRODED)	
3	

This inspection information is for reference only at "the inspection date" by SOGO. NOT to guarantee the condition of the actual machine.
この査定情報は『点検日時点』での参考資料であり、実際の機械の状態を保証するものではありません。