

INSPECTION SHEET 検品書
EXCAVATOR バックホー

INSPECTION DATE	2025/5/12	MAKE	KUBOTA	MODEL	RX-306E
SERIAL	KBCPZ48AAL3D27155		STAMP	KBCPZ48AAL3D27155	
HR METER	1279	HR	YEAR	YR	
CAB/CNP	ROPS CAB / <u>CAB</u> / ROPS CNP / CNP / NONE		SHOE	300G PADS	

ENGINE : MODEL		S/N	7LB4707
Oil leakage	<u>FAIR</u> • Attn		
Blow-By	<u>FAIR</u> • Attn	A LITTLE • MIDDLE • SEVERE	
Sound	<u>FAIR</u> • Attn		
Oil	<u>FAIR</u> • Attn		
Exhaust Color	<u>FAIR</u> • Attn		
US EPA	YES • <u>NO</u>		
MAIN PUMP			
Sound	<u>FAIR</u> • Attn		
Oil leakage	<u>FAIR</u> • Attn		
Power	<u>FAIR</u> • Attn		
COOLING SYSTEM			
Radiator	<u>FAIR</u> • Attn		
Oil Cooler	<u>FAIR</u> • Attn		
OPERATING SYSTEM			
Swing	<u>FAIR</u> • Attn		
Travel	<u>FAIR</u> • Attn		
INTERIOR See Photos. 写真参照			
INTERIOR COND.	<u>CLEAN</u> • FAIR • DIRTY		
Operator's Seat	<u>FAIR</u> • Attn		
Glasses	<u>FAIR</u> • Attn		
AirCon	<u>A/C</u> • H/C • H only • C only • None		
BOOM / ARM / BKT			
Boom	<u>FAIR</u> • Attn		
Boom Cylinder	<u>FAIR</u> • Attn		
Arm	<u>FAIR</u> • Attn		
Arm Cylinder	<u>FAIR</u> • Attn		
BKT	<u>FAIR</u> • Attn		
BKT Cylinder	<u>FAIR</u> • Attn		

UNDERCARRIAGE : See Photos. 写真参照	
RUST (5: NONE, 4: A LITTLE, 3: MIDDLE, 2: MUCH, 1: CORRODED)	4
COMMENT	
BKT	<u>STD</u> / SLOPE / NARROW / SKELETON / OTHER ()
Lever	LONG • <u>WRIST</u>
Multi	<u>MULTI</u> • 2 • NO
ARM-CRANE	<u>YES</u> • NO
BLADE	<u>YES</u> • NO
OFFSET	<u>YES</u> • NO
OFFSET Cylinder	<u>FAIR</u> • Attn
Piping	YES • <u>NO</u> Breaker only • Multi
COMMENT	
RUST of BODY (5: NONE, 4: A LITTLE, 3: MIDDLE, 2: MUCH, 1: CORRODED)	
4	

This inspection information is for reference only at "the inspection date" by SOGO. NOT to guarantee the condition of the actual machine.
この査定情報は『点検日時点』での参考資料であり、実際の機械の状態を保証するものではありません。