

INSPECTION SHEET 検品書
EXCAVATOR バックホー

INSPECTION DATE	2025/5/30	MAKE	KUBOTA	MODEL	RX-306E
SERIAL	KBCPZ48ACL3D27162			STAMP	KBCPZ48ACL3D27162
HR METER	1025	HR	YEAR	YR	
CAB/CNP	ROPS CAB / CAB / ROPS CNP / CNP / NONE			SHOE	300G PADS

ENGINE : MODEL		S/N	7LB4111
Oil leakage	☒ FAIR · Attn		
Blow-By	☒ FAIR · Attn	A LITTLE · MIDDLE · SEVERE	
Sound	☒ FAIR · Attn		
Oil	☒ FAIR · Attn		
Exhaust Color	☒ FAIR · Attn		
US EPA	YES · ☒ NO		
MAIN PUMP			
Sound	☒ FAIR · Attn		
Oil leakage	☒ FAIR · Attn		
Power	☒ FAIR · Attn		
COOLING SYSTEM			
Radiator	☒ FAIR · Attn		
Oil Cooler	☒ FAIR · Attn		
OPERATING SYSTEM			
Swing	☒ FAIR · Attn	ガタあり SWING: LOOSE	
Travel	☒ FAIR · Attn		
INTERIOR See Photos. 写真参照			
INTERIOR COND.	☒ CLEAN	FAIR · DIRTY	
Operator's Seat	☒ FAIR · Attn		
Glasses	☒ FAIR · Attn		
AirCon	☒ A/C	H/C · H only · C only · None	
BOOM / ARM / BKT			
Boom	☒ FAIR · Attn		
Boom Cylinder	☒ FAIR · Attn		
Arm	☒ FAIR · Attn		
Arm Cylinder	☒ FAIR · Attn		
BKT	☒ FAIR · Attn		
BKT Cylinder	☒ FAIR · Attn		

UNDERCARRIAGE : See Photos. 写真参照	
RUST (5: NONE, 4: A LITTLE, 3: MIDDLE, 2: MUCH, 1: CORRODED)	4
COMMENT	
BKT	☒ STD / SLOPE / NARROW / SKELETON / OTHER ()
Lever	LONG · ☒ WRIST
Multi	☒ MULTI · 2 · NO
ARM-CRANE	☒ YES · NO
BLADE	☒ YES · NO
OFFSET	☒ YES · NO
OFFSET Cylinder	☒ FAIR · Attn
Piping	YES · ☒ NO Breaker only · Multi
COMMENT	
RUST of BODY (5: NONE, 4: A LITTLE, 3: MIDDLE, 2: MUCH, 1: CORRODED)	5

This inspection information is for reference only at "the inspection date" by SOGO. NOT to guarantee the condition of the actual machine.
この査定情報は『点検日時点』での参考資料であり、実際の機械の状態を保証するものではありません。