

INSPECTION SHEET 検品書
EXCAVATOR バックホー

INSPECTION DATE	2025/5/27	MAKE	KOMATSU	MODEL	PC120-8
SERIAL	84311		STAMP	UNREADABLE	
HR METER	6463	HR	YEAR	YR	
CAB/CNP	(ROPS CAB) / CAB / ROPS CNP / CNP / NONE		SHOE	500G	

ENGINE : MODEL		4D95LE-5	S/N	579125
Oil leakage	FAIR · Attn			
Blow-By	FAIR · Attn	A LITTLE · MIDDLE · SEVERE		
Sound	FAIR · Attn			
Oil	FAIR · Attn			
Exhaust Color	FAIR · Attn			
US EPA	YES · NO			
MAIN PUMP				
Sound	FAIR · Attn			
Oil leakage	FAIR · Attn			
Power	FAIR · Attn			
COOLING SYSTEM				
Radiator	FAIR · Attn			
Oil Cooler	FAIR · Attn			
OPERATING SYSTEM				
Swing	FAIR · Attn	ガタあり SWING: LOOSE		
Travel	FAIR · Attn			
INTERIOR See Photos. 写真参照				
INTERIOR COND.	CLEAN · FAIR · DIRTY			
Operator's Seat	FAIR · Attn			
Glasses	FAIR · Attn			
AirCon	A/C · H/C · H only · C only · None			
BOOM / ARM / BKT				
Boom	FAIR · Attn			
Boom Cylinder	FAIR · Attn	左側油漏れあり LEFT CYLINDER: OIL LEAKING		
Arm	FAIR · Attn	ガタあり LOOSE		
Arm Cylinder	FAIR · Attn			
BKT	FAIR · Attn	亀裂あり CRACKED		
BKT Cylinder	FAIR · Attn			

[illegible]

This inspection information is for reference only at "the inspection date" by SOGO. NOT to guarantee the condition of the actual machine.

この査定情報は『点検日時点』での参考資料であり、実際の機械の状態を保証するものではありません。