

INSPECTION SHEET 検品書
ROUGH TERRAIN CRANE ラフタークレーン

INSPECTION DATE	2025/5/13	MAKE	KATO	MODEL	KR-25H-ⅢL
SERIAL No.	PLATE : 243485		STAMP : NOT FOUND		
HR METER	30820	HR	Odometer	101065	km
TIRE SIZE	16.00-25		YEAR	YR	

ENGINE : MODEL		S/N
Oil leakage	FAIR • Attn	
Blow-By	FAIR • Attn	A LITTLE • MIDDLE • SEVERE
Sound	FAIR • Attn	
Oil	FAIR • Attn	
Exhaust Color	FAIR • Attn	
OPERATION PUMP		
Sound	FAIR • Attn	
Oil leakage	FAIR • Attn	
Power	FAIR • Attn	
COOLING SYSTEM		
Radiator	FAIR • Attn	
Oil Cooler	FAIR • Attn	
OPERATING SYSTEM		
Computer	OK • NG	
Swing	FAIR • Attn	
Travel	FAIR • Attn	
TRANSMISSION		
Transmission	FAIR • Attn	
No. OF GEARS	4 GEAR	
4WD	4WD • 6WD	
INTERIOR See Photos. 写真参照		
INTERIOR COND.	CLEAN • FAIR • DIRTY	
Operator's Seat	FAIR • Attn	破れあり TORN
Glasses	FAIR • Attn	
AirCon	A/C • H/C • H only • C only • None	
COMMENT		

BOOM					
No. of Section		4		SECTIONS	
CRACK/ENFORCEMENT	FAIR	▪ Attn			
DERRICKING CYL.	FAIR	▪ Attn			
EXTENSION CYL.	FAIR	▪ Attn			
JIB	YES	▪ NO			
JIB TYPE	STD	▪ PWR			
MAIN & SUB WIRE	YES	▪ NO			
HOOK	25t, BALL				
UNDERCARRIAGE : See Photos. 写真参照					
RUST (5: NONE, 4: A LITTLE, 3: MIDDLE, 2: MUCH, 1: CORRODED)					2
TIRE WEAR	FAIR • WORN • UNEVEN WEAR				
COMMENT					
OUTRIGGERS					
OUTRIGGERS	X	• (H)		*1	
OUTRIGGERS COND.	FAIR	▪ Attn			
Oil leakage (JACK CYL.)	FRONT	L ▪ R		REAR	L ▪ R
Oil leakage (SLIDE CYL.)	FRONT	L ▪ R		REAR	L ▪ R
COMMENT					
右後ろサイドにアクセルあり					
W/ANOTHER ACCELERATOR AT REAR RIGHT SIDE OF BODY					
*1 右Rアウトリガー自然降下あり					
*1 REAR RIGHT JACK CYLINDER: HYDRAULIC DRIFT					
RUST of BODY (5: NONE, 4: A LITTLE, 3: MIDDLE, 2: MUCH, 1: CORRODED)					2

This inspection information is for reference only at "the inspection date" by SOGO. NOT to guarantee the condition of the actual machine.

この査定情報は『点検日時点』での参考資料であり、実際の機械の状態を保証するものではありません。