

INSPECTION SHEET 検品書
WHEEL LOADER タイヤショベル

INSPECTION DATE	2025/5/19	MAKE	HITACHI	MODEL	ZW140
SERIAL	RYU4FC00J00005697			STAMP	S61-05697
HR METER	14470	HR	Odometer	37389	km
CAB/CNP	ROPS CAB / CAB / ROPS CNP / CNP / NONE			TIRE SIZE	17.5-25

ENGINE : MODEL QB4		S/N 26104156
Oil leakage	☒ FAIR	Attn
Blow-By	☒ FAIR	A LITTLE · MIDDLE · SEVERE
Sound	☒ FAIR	Attn
Oil	☒ FAIR	油量多い MUCH OIL
Exhaust Color	☒ FAIR	Attn
US EPA	YES	☒ NO
OPERATION PUMP		
Sound	☒ FAIR	Attn
Oil leakage	☒ FAIR	Attn
Power	☒ FAIR	Attn
COOLING SYSTEM		
Radiator	☒ FAIR	Attn
Oil Cooler	☒ FAIR	Attn
TRANSMISSION & TRAVEL		
T/M TYPE	☒ PS	DD
Transmission	☒ FAIR	Attn
Travel	☒ FAIR	Attn
FOOT BRAKE	☒ FAIR	Attn
PARKING BRAKE	☒ FAIR	Attn
INTERIOR See Photos. 写真参照		
INTERIOR COND.	CLEAN · ☒ FAIR ·	DIRTY
Operator's Seat	☒ FAIR	Attn
Glasses	☒ FAIR	Attn
AirCon	☒ A/C · H/C · H only · C only · None	
FRONT & CYLINDERS		
Arm	☒ FAIR	Attn
Bell crank	☒ FAIR	Attn
Bucket	☒ FAIR	Attn
Articulate	☒ FAIR	Attn

UNDERCARRIAGE : See Photos. 写真参照	
RUST (5: NONE, 4: A LITTLE, 3: MIDDLE, 2: MUCH, 1: CORRODED)	4
TIRE WEAR	FAIR · WORN · ☒ UNEVEN WEAR
COMMENT	
STEERING TYPE ☒ WHEEL STEERING / ☐ COMMAND STEERING / ☐ LEVER STEERING	
RIDE CONTROL	YES · ☒ NO
ATTACHMENTS	
STD BKT	☒ YES · OTHER
BLADE	YES · ☒ NO Piping for Tilt YES · ☒ NO
COMMENT	
RUST of BODY (5: NONE, 4: A LITTLE, 3: MIDDLE, 2: MUCH, 1: CORRODED)	
4	

This inspection information is for reference only at "the inspection date" by SOGO. NOT to guarantee the condition of the actual machine.
この査定情報は『点検日時点』での参考資料であり、実際の機械の状態を保証するものではありません。