

INSPECTION SHEET 検品書
BULLDOZER ブルドーザー

INSPECTION DATE	2025/5/16	MAKE	CAT	MODEL	D5H
SERIAL	2SD04146			STAMP	2SD04146
HR METER	E7578	HR	SHOE	860LGP	YEAR YR
BLADE	STRAIGHT (ST/TILT) PAT / ANGLE / OTHER			CAB/CNP	ROPS CAB / CAB / ROPS CNP / CNP / NONE

ENGINE : MODEL		S/N	12Z52767
Oil leakage	(FAIR) · Attn		
Blow-By	(FAIR) · Attn	A LITTLE · MIDDLE · SEVERE	
Sound	(FAIR) · Attn		
Oil	(FAIR) · Attn		
Exhaust Color	(FAIR) · Attn		
US EPA	YES · (NO)		
OPERATION PUMP			
Sound	(FAIR) · Attn		
Oil leakage	(FAIR) · Attn		
Power	(FAIR) · Attn		
COOLING SYSTEM			
Radiator	(FAIR) · Attn		
Oil Cooler	FAIR · Attn		
TRANSMISSION & TRAVEL			
T/M TYPE	PS · (DD)	DIFF. STEERING	YES · (NO)
Transmission	(FAIR) · Attn		
Travel	(FAIR) · Attn		
INTERIOR See Photos. 写真参照			
INTERIOR COND.	CLEAN · FAIR · (DIRTY)		
Operator's Seat	(FAIR) · Attn	破れあり CUTS	
Glasses	(FAIR) · Attn		
AirCon	A/C · (H/C) · H only · C only · None		
BLADE & CYLINDERS			
BLADE	(FAIR) · Attn		
CYLD.(R)	(FAIR) · Attn		
CYLD.(L)	(FAIR) · Attn		
TILT CYLD	(FAIR) · Attn		
ANGLE CYLD	(FAIR) · Attn		

UNDERCARRIAGE See Photos. 写真参照			
RUST (5: NONE, 4: A LITTLE, 3: MIDDLE, 2: MUCH, 1: CORRODED)			1
COMMENT			
Ripper	MULTI · S/S	Shanks	PCS
Ripper CYLD.	FAIR · Attn		
EQUALIZER BAR	FAIR · Attn		
COMMENT			
HRメーターストップ HR METER: STOPPED			
RUST of BODY (5: NONE, 4: A LITTLE, 3: MIDDLE, 2: MUCH, 1: CORRODED)			2

This inspection information is for reference only at "the inspection date" by SOGO. NOT to guarantee the condition of the actual machine.
 この査定情報は『点検日時点』での参考資料であり、実際の機械の状態を保証するものではありません。