

INSPECTION SHEET 検品書
ROUGH TERRAIN CRANE ラフタークレーン

INSPECTION DATE	2025/5/30	MAKE	KATO	MODEL	KRM-13H
SERIAL No.	PLATE : 5910312		STAMP : KR130-0312		
HR METER	17878	HR	Odometer	102454	km
TIRE SIZE	275/80R22.5		YEAR	YR	

ENGINE : MODEL		S/N	
Oil leakage	FAIR • Attn		
Blow-By	FAIR • Attn	A LITTLE • MIDDLE • SEVERE	
Sound	FAIR • Attn		
Oil	FAIR • Attn		
Exhaust Color	FAIR • Attn		
OPERATION PUMP			
Sound	FAIR • Attn		
Oil leakage	FAIR • Attn		
Power	FAIR • Attn		
COOLING SYSTEM			
Radiator	FAIR • Attn		
Oil Cooler	FAIR • Attn		
OPERATING SYSTEM			
Computer	OK • NG		
Swing	FAIR • Attn		
Travel	FAIR • Attn		
TRANSMISSION			
Transmission	FAIR • Attn		
No. OF GEARS	4	GEARS	
4WD	4WD • 6WD		
INTERIOR See Photos. 写真参照			
INTERIOR COND.	CLEAN • FAIR •	DIRTY	
Operator's Seat	FAIR • Attn		
Glasses	FAIR • Attn		
AirCon	A/C • H/C • H only • C only • None		
COMMENT			

BOOM									
No. of Section		6		SECTIONS					
CRACK/ENFORCEMENT		FAIR		▪ Attn					
DERRICKING CYL.		FAIR		▪ Attn		にじみあり OIL OOZING			
EXTENSION CYL.		FAIR		▪ Attn					
JIB		YES		▪ NO					
JIB TYPE		STD		▪ PWR					
MAIN & SUB WIRE		YES		▪ NO					
HOOK		13t, BALL							
UNDERCARRIAGE : See Photos. 写真参照									
RUST (5: NONE, 4: A LITTLE, 3: MIDDLE, 2: MUCH, 1: CORRODED)								2	
TIRE WEAR		FAIR ▪ WORN ▪ UNEVEN WEAR							
COMMENT									
OUTRIGGERS									
OUTRIGGERS		X		▪ H					
OUTRIGGERS COND.		FAIR		▪ Attn					
Oil leakage (JACK CYL.)		FRONT		L ▪ R		REAR		L ▪ R	
Oil leakage (SLIDE CYL.)		FRONT		L ▪ R		REAR		L ▪ R	
COMMENT									
RUST of BODY (5: NONE, 4: A LITTLE, 3: MIDDLE, 2: MUCH, 1: CORRODED)								3	

This inspection information is for reference only at "the inspection date" by SOGO. NOT to guarantee the condition of the actual machine.
この査定情報は『点検日時点』での参考資料であり、実際の機械の状態を保証するものではありません。