

INSPECTION SHEET 検品書

TRUCK CRANE / ALL TERRAIN CRANE トラッククレーン / オールテレーンクレーン

INSPECTION DATE	2025/6/10	CATEGORY	TRUCK CRANE / ALL TERRAIN CRANE						
MAKE	KATO		MODEL	NK-75M-V					
SERIAL	3010540		STAMP	FC3JDA-10064					
HR METER	UNKNOWN	HR	Odometer	178525	km	YEAR		YR	
CHASSIS	MODEL	KC-FC3JDAA	No.	10064	TIRE	7.50R16			

ENGINE(CRANE) : MODEL		S/N	
Oil leakage	FAIR · Attn		
Blow-By	FAIR · Attn	A LITTLE · MIDDLE · SEVERE	
Sound	FAIR · Attn		
Oil	FAIR · Attn		
Exhaust Color	FAIR · Attn		
ENGINE(CHASSIS) : MODEL		J07C	S/N
Oil leakage	FAIR · Attn		
Blow-By	FAIR · Attn	A LITTLE · MIDDLE · SEVERE	
Sound	FAIR · Attn		
Oil	FAIR · Attn		
Exhaust Color	FAIR · Attn		
OPERATION PUMP			
Sound	FAIR · Attn		
Oil leakage	FAIR · Attn		
Power	FAIR · Attn		
COOLING SYSTEM			
Radiator	FAIR · Attn		
Oil Cooler	FAIR · Attn		
OPERATING SYSTEM			
Computer	OK · NG		
Swing	FAIR · Attn		
Travel	FAIR · Attn		
TRANSMISSION & TRAVEL			
T/M TYPE	AT · MT	No. OF GEARS	5 GEARS
Transmission	FAIR · Attn		
No. of DRIVE WHEELS	2 WD		
Travel	FAIR · Attn		
FOOT BRAKE	FAIR · Attn		
PARKING BRAKE	FAIR · Attn		
INTERIOR See Photos. 写真参照			
INTERIOR COND.	CLEAN · FAIR · DIRTY		
Operator's Seat	FAIR · Attn	破れあり	A LITTLE DAMAGED
Glasses	FAIR · Attn		
AirCon	A/C · H/C · H only · C only · NONE		

CRANE		
WEIGHT		
HOOK	4.9t, BALL	
BOOM		
MAIN BOOM		
BOOM TOTAL		
No. of Section	4 SECTIONS	
TOP SHEAVE	YES · NO	
JIB	STD · PWR	
UNDERCARRIAGE : See Photos. 写真参照		
RUST (5: NONE, 4: A LITTLE, 3: MIDDLE, 2: MUCH, 1: CORRODED)	3	
TIRE WEAR	FAIR · WORN · UNEVEN WEAR	
COMMENT		
OUTRIGGERS		
OUTRIGGERS	FAIR · Attn H-TYPE *1	
FRONT JACK	YES · NO	
COMMENT		
過巻装置不良 OVERWINDING PREVENTION: MALFUNCTION		
クレーン部アクセル吹けない UNABLE TO REV UP IN CRANE CAB		
起伏シリンダーロッド傷あり DERRICKING CYLINDER: SCRATCHED		
エアー漏れあり AIR LEAKING		
*1 左フストロックセンサー不良		
*1 FRONT LEFT OUTRIGGER EXTENSION SENSOR: MALFUNCTION		
RUST of BODY (5: NONE, 4: A LITTLE, 3: MIDDLE, 2: MUCH, 1: CORRODED)		3

This inspection information is for reference only at "the inspection date" by SOGO. NOT to guarantee the condition of the actual machine.
この査定情報は『点検日時点』での参考資料であり、実際の機械の状態を保証するものではありません。