

INSPECTION SHEET 検品書
EXCAVATOR バックホー

INSPECTION DATE	2025/6/17	MAKE	CAT	MODEL	312D
SERIAL	CAT0312DJFBJ01762		STAMP	CAT0312DJFBJ01762	
HR METER	5534	HR	YEAR	YR	
CAB/CNP	ROPS CAB / CAB / ROPS CNP / CNP / NONE		SHOE	500G	

ENGINE : MODEL		C4.2	S/N	JKH13389
Oil leakage	FAIR	Attn		
Blow-By	FAIR	Attn	A LITTLE · MIDDLE · SEVERE	
Sound	FAIR	Attn		
Oil	FAIR	Attn	少ない NOT ENOUGH	
Exhaust Color	FAIR	Attn		
US EPA	YES	NO		
MAIN PUMP				
Sound	FAIR	Attn		
Oil leakage	FAIR	Attn		
Power	FAIR	Attn		
COOLING SYSTEM				
Radiator	FAIR	Attn		
Oil Cooler	FAIR	Attn		
OPERATING SYSTEM				
Swing	FAIR	Attn		
Travel	FAIR	Attn		
INTERIOR See Photos. 写真参照				
INTERIOR COND.	CLEAN	FAIR	DIRTY	
Operator's Seat	FAIR	Attn		
Glasses	FAIR	Attn		
AirCon	A/C	H/C	H only	C only
				None
BOOM / ARM / BKT				
Boom	FAIR	Attn		
Boom Cylinder	FAIR	Attn	左にじみあり LEFT CYLINDER: OIL OOZING	
Arm	FAIR	Attn		
Arm Cylinder	FAIR	Attn	にじみあり OIL OOZING	
BKT	FAIR	Attn		
BKT Cylinder	FAIR	Attn		

UNDERCARRIAGE :						See Photos.		写真参照	
RUST (5: NONE, 4: A LITTLE, 3: MIDDLE, 2: MUCH, 1: CORRODED)								3	
COMMENT									
BKT	(STD)	/ SLOPE / NARROW / SKELETON / OTHER()							
Lever	LONG	▪	(WRIST)						
Multi	(MULTI)	▪	2	▪	NO				
ARM-CRANE	(YES)	▪	NO						
BLADE	YES	▪	(NO)						
OFFSET	YES	▪	(NO)						
OFFSET Cylinder	FAIR	▪	Attn						
Piping	(YES)	▪	NO	Breaker only	▪	(Multi)			
COMMENT									
運転席下底板油漏れ小 BOTTOM OF CAB: OIL LEAKING									
RUST of BODY (5: NONE, 4: A LITTLE, 3: MIDDLE, 2: MUCH, 1: CORRODED)									3

This inspection information is for reference only at "the inspection date" by SOGO. NOT to guarantee the condition of the actual machine.

この査定情報は『点検日時点』での参考資料であり、実際の機械の状態を保証するものではありません。