

INSPECTION SHEET 検品書
WHEEL LOADER タイヤショベル

INSPECTION DATE	2025/5/28	MAKE	KAWASAKI	MODEL	45ZA		
SERIAL	45N1-2236			STAMP	45N1-2236		
HR METER	3617 / 3509	HR	Odometer	-	km	YEAR	YR
CAB/CNP	ROPS CAB / CAB / ROPS CNP / CNP / NONE			TIRE SIZE	17.5/65-20		

ENGINE : MODEL		S/N
Oil leakage	FAIR • Attn	
Blow-By	FAIR • Attn	A LITTLE • MIDDLE • SEVERE
Sound	FAIR • Attn	
Oil	FAIR • Attn	
Exhaust Color	FAIR • Attn	
US EPA	YES • NO	
OPERATION PUMP		
Sound	FAIR • Attn	
Oil leakage	FAIR • Attn	
Power	FAIR • Attn	
COOLING SYSTEM		
Radiator	FAIR • Attn	
Oil Cooler	FAIR • Attn	
TRANSMISSION & TRAVEL		
T/M TYPE	PS • DD	
Transmission	FAIR • Attn	
Travel	FAIR • Attn	
FOOT BRAKE	FAIR • Attn	
PARKING BRAKE	FAIR • Attn	
INTERIOR See Photos. 写真参照		
INTERIOR COND.	CLEAN • FAIR • DIRTY	
Operator's Seat	FAIR • Attn	
Glasses	FAIR • Attn	
AirCon	A/C • H/C • H only • C only • None	
FRONT & CYLINDERS		
Arm	FAIR • Attn	*1
Bell crank	FAIR • Attn	
Bucket	FAIR • Attn	*2
Articulate	FAIR • Attn	

UNDERCARRIAGE : See Photos. 写真参照	
RUST (5: NONE, 4: A LITTLE, 3: MIDDLE, 2: MUCH, 1: CORRODED)	3
TIRE WEAR	FAIR • WORN • UNEVEN WEAR
COMMENT	
STEERING TYPE WHEEL STEERING / COMMAND STEERING / LEVER STEERING	
RIDE CONTROL	YES • NO
ATTACHMENTS	
STD BKT	YES • OTHER マルチプラウ MULTI PLOW
BLADE	YES • NO Piping for Tilt YES • NO
COMMENT	
ワンタッチ付 W/ONE-TOUCH	
付属品:スタンダードバケット、タイヤ4本	
STANDARD BUCKET & 4 PIECES OF TIRES: AS SPARE	
*1 左シリンダー油漏れあり LEFT CYLINDER: OIL LEAKING	
*2 シリンダー油漏れ小、サビあり CYLINDER: OIL LEAKING, RUSTY	
RUST of BODY (5: NONE, 4: A LITTLE, 3: MIDDLE, 2: MUCH, 1: CORRODED)	
3	

This inspection information is for reference only at "the inspection date" by SOGO. NOT to guarantee the condition of the actual machine.
この査定情報は『点検日時点』での参考資料であり、実際の機械の状態を保証するものではありません。