

INSPECTION SHEET 検品書
EXCAVATOR バックホー

INSPECTION DATE	2025/6/5	MAKE	KOMATSU	MODEL	PC58UU-5
SERIAL	25455		STAMP	KMTPC221H04025455	
HR METER	5234	HR	YEAR	YR	
CAB/CNP	ROPS CAB / CAB / ROPS CNP / CNP / NONE		SHOE	400G PADS	

ENGINE : MODEL						4D88E							S/N									21376									
Oil leakage		FAIR		Attn																											
Blow-By		FAIR		Attn		A LITTLE · MIDDLE · SEVERE																									
Sound		FAIR		Attn																											
Oil		FAIR		Attn																											
Exhaust Color		FAIR		Attn																											
US EPA		YES		NO																											
MAIN PUMP																															
Sound		FAIR		Attn																											
Oil leakage		FAIR		Attn																											
Power		FAIR		Attn																											
COOLING SYSTEM																															
Radiator		FAIR		Attn																											
Oil Cooler		FAIR		Attn																											
OPERATING SYSTEM																															
Swing		FAIR		Attn																											
Travel		FAIR		Attn																											
INTERIOR See Photos. 写真参照																															
INTERIOR COND.				CLEAN	· FAIR ·			DIRTY																							
Operator's Seat				FAIR	Attn			破れあり CUTS																							
Glasses				FAIR		Attn																									
AirCon				A/C	· H/C ·			H only	· C only ·			None																			
BOOM / ARM / BKT																															
Boom		FAIR		Attn																											
Boom Cylinder		FAIR		Attn																											
Arm		FAIR		Attn																											
Arm Cylinder		FAIR		Attn																											
BKT		FAIR		Attn			破れ大 MUCH CRACKED																								
BKT Cylinder		FAIR		Attn																											

UNDERCARRIAGE :										See Photos. 写真参照									
RUST (5: NONE, 4: A LITTLE, 3: MIDDLE, 2: MUCH, 1: CORRODED)															3				
COMMENT																			
BKT	STD / SLOPE / NARROW / SKELETON / OTHER()																		
Lever	LONG	· WRIST																	
Multi	MULTI	· 2 · NO																	
ARM-CRANE	YES	· NO			フック部分回らない HOOK: UNABLE TO ROTATE														
BLADE	YES	· NO																	
OFFSET	YES	· NO																	
OFFSET Cylinder	FAIR	· Attn																	
Piping	YES	· NO			Breaker only Multi														
COMMENT																			
セーフティレバー固着気味 SAFETY LEVER: A LITTLE STUCK																			
ロングアーム LONG ARM																			
RUST of BODY (5: NONE, 4: A LITTLE, 3: MIDDLE, 2: MUCH, 1: CORRODED)															4				

This inspection information is for reference only at "the inspection date" by SOGO. NOT to guarantee the condition of the actual machine.

この査定情報は『点検日時点』での参考資料であり、実際の機械の状態を保証するものではありません。