

INSPECTION SHEET 検品書
WHEEL LOADER タイヤショベル

INSPECTION DATE	2025/5/29	MAKE	CAT	MODEL	990K
SERIAL	CAT0990KVDJK00229			STAMP	CAT0990KVDJK00229
HR METER	23297	HR	Odometer	138918	km
CAB/CNP	ROPS CAB / CAB / ROPS CNP / CNP / NONE	TIRE SIZE	45/65R39		

ENGINE : MODEL S/N Oil leakage ☒ FAIR · Attn Blow-By ☒ FAIR · Attn A LITTLE · MIDDLE · SEVERE Sound ☒ FAIR · Attn Oil ☒ FAIR · Attn Exhaust Color ☒ FAIR · Attn US EPA YES · ☒ NO OPERATION PUMP Sound ☒ FAIR · Attn Oil leakage ☒ FAIR · Attn Power ☒ FAIR · Attn COOLING SYSTEM Radiator ☒ FAIR · Attn Oil Cooler ☒ FAIR · Attn TRANSMISSION & TRAVEL T/M TYPE ☒ PS · DD Transmission ☒ FAIR · Attn Travel ☒ FAIR · Attn FOOT BRAKE ☒ FAIR · Attn PARKING BRAKE ☒ FAIR · Attn INTERIOR See Photos. 写真参照 INTERIOR COND. CLEAN · ☒ FAIR · DIRTY Operator's Seat ☒ FAIR · Attn Glasses ☒ FAIR · Attn *1 AirCon ☒ A/C · H/C · H only · C only · None FRONT & CYLINDERS Arm ☒ FAIR · Attn 左シリンダー油漏れあり LEFT CYLINDER: OIL LEAKING Bell crank ☒ FAIR · Attn Bucket ☒ FAIR · Attn Articulate ☒ FAIR · Attn	UNDERCARRIAGE : See Photos. 写真参照 RUST (5: NONE, 4: A LITTLE, 3: MIDDLE, 2: MUCH, 1: CORRODED) 4 TIRE WEAR FAIR · WORN ☒ UNEVEN WEAR COMMENT STEERING TYPE WHEEL STEERING / COMMAND STEERING ☒ LEVER STEERING RIDE CONTROL ☒ YES · NO ATTACHMENTS STD BKT ☒ YES · OTHER BLADE YES · ☒ NO Piping for Tilt YES · ☒ NO COMMENT *1 右Fひび割れあり RIGHT PART OF WINDSHIELD: CRACKED RUST of BODY (5: NONE, 4: A LITTLE, 3: MIDDLE, 2: MUCH, 1: CORRODED) 4
---	--

This inspection information is for reference only at "the inspection date" by SOGO. NOT to guarantee the condition of the actual machine.
この査定情報は『点検日時点』での参考資料であり、実際の機械の状態を保証するものではありません。