

INSPECTION SHEET 検品書
EXCAVATOR バックホー

INSPECTION DATE	2025/5/29	MAKE	HITACHI	MODEL	ZX250LCH-5B
SERIAL	HCMDCAA3K00030532			STAMP	HCMDCAA3K00030532
HR METER	16145	HR	YEAR	YR	
CAB/CNP	ROPS CAB / CAB / ROPS CNP / CNP / NONE			SHOE	600G

ENGINE : MODEL 4HK1 S/N 731436

Oil leakage	FAIR	Attn	
Blow-By	FAIR	Attn	A LITTLE · MIDDLE · SEVERE
Sound	FAIR	Attn	
Oil	FAIR	Attn	
Exhaust Color	FAIR	Attn	
US EPA	YES	NO	

MAIN PUMP

Sound	FAIR	Attn	
Oil leakage	FAIR	Attn	
Power	FAIR	Attn	

COOLING SYSTEM

Radiator	FAIR	Attn	
Oil Cooler	FAIR	Attn	

OPERATING SYSTEM

Swing	FAIR	Attn	ガタあり SWING: LOOSE
Travel	FAIR	Attn	

INTERIOR See Photos. 写真参照

INTERIOR COND.	CLEAN	FAIR	DIRTY
Operator's Seat	FAIR	Attn	破れあり TORN
Glasses	FAIR	Attn	
AirCon	A/C	H/C	H only · C only · None

BOOM / ARM / BKT

Boom	FAIR	Attn	
Boom Cylinder	FAIR	Attn	
Arm	FAIR	Attn	ガタあり LOOSE
Arm Cylinder	FAIR	Attn	にじみ小 OIL Oozing
BKT	FAIR	Attn	ガタあり LOOSE
BKT Cylinder	FAIR	Attn	にじみ小 OIL Oozing

UNDERCARRIAGE : See Photos. 写真参照

RUST (5: NONE, 4: A LITTLE, 3: MIDDLE, 2: MUCH, 1: CORRODED)	3
--	---

COMMENT

.....

.....

.....

.....

BKT (STD / SLOPE / NARROW / SKELETON / OTHER ()

Lever LONG · WRIST

Multi MULTI · 2 · NO

ARM-CRANE YES · NO

BLADE YES · NO

OFFSET YES · NO

OFFSET Cylinder FAIR · Attn

Piping YES · NO Breaker only · Multi

COMMENT

マフラフィルタ、E/G異常警告あり

WARNINGS DISPLAY FOR EXHAUST FILTER & ENGINE

.....

.....

.....

.....

.....

.....

.....

.....

RUST of BODY (5: NONE, 4: A LITTLE, 3: MIDDLE, 2: MUCH, 1: CORRODED) 3

This inspection information is for reference only at "the inspection date" by SOGO. NOT to guarantee the condition of the actual machine.
この査定情報は『点検日時点』での参考資料であり、実際の機械の状態を保証するものではありません。