

INSPECTION SHEET 検品書
EXCAVATOR バックホー

INSPECTION DATE	2025/6/5	MAKE	KUBOTA	MODEL	KX-040
SERIAL	11426		STAMP	KX040-11426	
HR METER	1506	HR	YEAR	1992	YR
CAB/CNP	ROPS CAB / CAB / ROPS CNP / CNP / NONE		SHOE	400R	

ENGINE : MODEL	S/N	15749
Oil leakage	FAIR · Attn	
Blow-By	FAIR · Attn	A LITTLE · MIDDLE · SEVERE
Sound	FAIR · Attn	
Oil	FAIR · Attn	
Exhaust Color	FAIR · Attn	
US EPA	YES · NO	

MAIN PUMP

Sound	FAIR · Attn	
Oil leakage	FAIR · Attn	
Power	FAIR · Attn	

COOLING SYSTEM

Radiator	FAIR · Attn	
Oil Cooler	FAIR · Attn	

OPERATING SYSTEM

Swing	FAIR · Attn	
Travel	FAIR · Attn	

INTERIOR See Photos. 写真参照

INTERIOR COND.	CLEAN ▪ FAIR ▪ DIRTY				
Operator's Seat	FAIR ▪	Attn			
Glasses	FAIR ▪	Attn			
AirCon	A/C ▪	H/C ▪	H only ▪	C only ▪	None

BOOM / ARM / BKT

Boom	FAIR	Attn	ガタあり LOOSE
Boom Cylinder	FAIR	Attn	サビあり RUSTY
Arm	FAIR	Attn	ヘコミあり DENT
Arm Cylinder	FAIR	Attn	サビあり RUSTY
BKT	FAIR	Attn	
BKT Cylinder	FAIR	Attn	ロッド傷あり ROD: SCRATCHED

UNDERCARRIAGE : See Photos. 写真参照

RUST (5: NONE, 4: A LITTLE, 3: MIDDLE, 2: MUCH, 1: CORRODED)	3
---	----------

COMMENT

BKT	STD / SLOPE / NARROW / SKELETON (OTHER) (FORK GRAB)
-----	---

Lever	LONG	•	WRIST
-------	------	---	-------

Multi	MULTI • 2 • NO
-------	----------------

ARM-CRANE	YES	☒ NO
-----------	-----	-------------------------------------

BLADE	YES • NO	
-------	----------	--

OFFSET	YES • NO	
--------	-----------------	--

OFFSET Cylinder	FAIR ▪ Attn	
-----------------	-------------	--

Piping	YES ▪ NO	Breaker only ▪ Multi
--------	-----------------	-----------------------------

COMMENT

付屬品:スタンダードバケツ STANDARD BUCKET AS SPARE

[illegible]

RUST of BODY (5: NONE, 4: A LITTLE, 3: MIDDLE, 2: MUCH, 1: CORRODED) **2**

This inspection information is for reference only at "the inspection date" by SOGO. NOT to guarantee the condition of the actual machine.

この査定情報は『点検日時点』での参考資料であり、実際の機械の状態を保証するものではありません。