

INSPECTION SHEET 検品書
EXCAVATOR バックホー

INSPECTION DATE	2025/6/5	MAKE	HITACHI	MODEL	EX60-5
SERIAL	1C1P052748		STAMP	1C1P052748	
HR METER	4758	HR	YEAR	YR	
CAB/CNP	ROPS CAB / CAB / ROPS CNP / CNP / NONE		SHOE	450G	

ENGINE : MODEL		S/N	UNDERCARRIAGE : See Photos. 写真参照	
Oil leakage	FAIR • Attn		RUST (5: NONE, 4: A LITTLE, 3: MIDDLE, 2: MUCH, 1: CORRODED) 2	
Blow-By	FAIR • Attn	A LITTLE • MIDDLE • SEVERE	COMMENT	
Sound	FAIR • Attn			
Oil	FAIR • Attn			
Exhaust Color	FAIR • Attn			
US EPA	YES • NO			
MAIN PUMP			BKT STD / SLOPE / NARROW / SKELETON OTHER)	
Sound	FAIR • Attn		Lever	LONG • WRIST
Oil leakage	FAIR • Attn		Multi	MULTI • 2 • NO
Power	FAIR • Attn		ARM-CRANE	YES • NO
COOLING SYSTEM			BLADE	YES • NO
Radiator	FAIR • Attn		OFFSET	YES • NO
Oil Cooler	FAIR • Attn		OFFSET Cylinder	FAIR • Attn
OPERATING SYSTEM			Piping	YES • NO Breaker only • Multi
Swing	FAIR • Attn	ガタ大 SWING: MUCH LOOSE	COMMENT	
Travel	FAIR • Attn	右足遅い RIGHT TRACK: SLOW MOVING	アタッチメント: ストレンジャーバケット ATTACHMENT: THUMB BUCKET	
INTERIOR See Photos. 写真参照				
INTERIOR COND.	CLEAN • FAIR • DIRTY			
Operator's Seat	FAIR • Attn			
Glasses	FAIR • Attn			
AirCon	A/C • H/C • H only • C only • None			
BOOM / ARM / BKT				
Boom	FAIR • Attn			
Boom Cylinder	FAIR • Attn			
Arm	FAIR • Attn			
Arm Cylinder	FAIR • Attn			
BKT	FAIR • Attn			
BKT Cylinder	FAIR • Attn	にじみあり OIL OOZING	RUST of BODY (5: NONE, 4: A LITTLE, 3: MIDDLE, 2: MUCH, 1: CORRODED) 1	

This inspection information is for reference only at "the inspection date" by SOGO. NOT to guarantee the condition of the actual machine.

この査定情報は『点検日時点』での参考資料であり、実際の機械の状態を保証するものではありません。