

INSPECTION SHEET 検品書
BULLDOZER ブルドーザー

INSPECTION DATE	2025/5/29	MAKE	KOMATSU	MODEL	D20P-7E
SERIAL	81435			STAMP	D207E-81435
HR METER	2429	HR	SHOE	500LGP	YEAR YR
BLADE	STRAIGHT / ST/TILT / PAT / ANGLE / OTHER			CAB/CNP	ROPS CAB / CAB / ROPS CNP / CNP / NONE

<table style="width: 100%;"> <tr> <td style="width: 50%;">ENGINE : MODEL</td> <td style="width: 50%;">S/N</td> </tr> <tr> <td>Oil leakage</td> <td>FAIR · Attn</td> </tr> <tr> <td>Blow-By</td> <td>FAIR · Attn A LITTLE · MIDDLE · SEVERE</td> </tr> <tr> <td>Sound</td> <td>FAIR · Attn</td> </tr> <tr> <td>Oil</td> <td>FAIR · Attn</td> </tr> <tr> <td>Exhaust Color</td> <td>FAIR · Attn</td> </tr> <tr> <td>US EPA</td> <td>YES · NO</td> </tr> <tr> <td colspan="2">OPERATION PUMP</td> </tr> <tr> <td>Sound</td> <td>FAIR · Attn</td> </tr> <tr> <td>Oil leakage</td> <td>FAIR · Attn</td> </tr> <tr> <td>Power</td> <td>FAIR · Attn</td> </tr> <tr> <td colspan="2">COOLING SYSTEM</td> </tr> <tr> <td>Radiator</td> <td>FAIR · Attn</td> </tr> <tr> <td>Oil Cooler</td> <td>FAIR · Attn</td> </tr> <tr> <td colspan="2">TRANSMISSION & TRAVEL</td> </tr> <tr> <td>T/M TYPE</td> <td>PS · DD DIFF. STEERING YES · NO</td> </tr> <tr> <td>Transmission</td> <td>FAIR · Attn</td> </tr> <tr> <td>Travel</td> <td>FAIR · Attn</td> </tr> <tr> <td colspan="2">INTERIOR See Photos. 写真参照</td> </tr> <tr> <td>INTERIOR COND.</td> <td>CLEAN · FAIR · DIRTY</td> </tr> <tr> <td>Operator's Seat</td> <td>FAIR · Attn</td> </tr> <tr> <td>Glasses</td> <td>FAIR · Attn</td> </tr> <tr> <td>AirCon</td> <td>A/C · H/C · H only · C only · None</td> </tr> <tr> <td colspan="2">BLADE & CYLINDERS</td> </tr> <tr> <td>BLADE</td> <td>FAIR · Attn</td> </tr> <tr> <td>CYLD.(R)</td> <td>FAIR · Attn</td> </tr> <tr> <td>CYLD.(L)</td> <td>FAIR · Attn *1</td> </tr> <tr> <td>TILT CYLD</td> <td>FAIR · Attn</td> </tr> <tr> <td>ANGLE CYLD</td> <td>FAIR · Attn</td> </tr> </table>	ENGINE : MODEL	S/N	Oil leakage	FAIR · Attn	Blow-By	FAIR · Attn A LITTLE · MIDDLE · SEVERE	Sound	FAIR · Attn	Oil	FAIR · Attn	Exhaust Color	FAIR · Attn	US EPA	YES · NO	OPERATION PUMP		Sound	FAIR · Attn	Oil leakage	FAIR · Attn	Power	FAIR · Attn	COOLING SYSTEM		Radiator	FAIR · Attn	Oil Cooler	FAIR · Attn	TRANSMISSION & TRAVEL		T/M TYPE	PS · DD DIFF. STEERING YES · NO	Transmission	FAIR · Attn	Travel	FAIR · Attn	INTERIOR See Photos. 写真参照		INTERIOR COND.	CLEAN · FAIR · DIRTY	Operator's Seat	FAIR · Attn	Glasses	FAIR · Attn	AirCon	A/C · H/C · H only · C only · None	BLADE & CYLINDERS		BLADE	FAIR · Attn	CYLD.(R)	FAIR · Attn	CYLD.(L)	FAIR · Attn *1	TILT CYLD	FAIR · Attn	ANGLE CYLD	FAIR · Attn	<table style="width: 100%;"> <tr> <td colspan="2">UNDERCARRIAGE See Photos. 写真参照</td> </tr> <tr> <td>RUST (5: NONE, 4: A LITTLE, 3: MIDDLE, 2: MUCH, 1: CORRODED)</td> <td>3</td> </tr> <tr> <td colspan="2">COMMENT</td> </tr> <tr><td colspan="2"> </td></tr> <tr><td colspan="2"> </td></tr> <tr><td colspan="2"> </td></tr> <tr><td colspan="2"> </td></tr> <tr><td colspan="2"> </td></tr> <tr><td colspan="2"> </td></tr> <tr> <td>Ripper</td> <td>MULTI · S/S Shanks PCS</td> </tr> <tr> <td>Ripper CYLD.</td> <td>FAIR · Attn</td> </tr> <tr> <td>EQUALIZER BAR</td> <td>FAIR · Attn</td> </tr> <tr> <td colspan="2">COMMENT</td> </tr> <tr> <td colspan="2">*1 にじみ、メッキ剥がれあり OIL OOZING, COATING: A LITTLE PEELED</td> </tr> <tr><td colspan="2"> </td></tr> <tr><td colspan="2"> </td></tr> <tr><td colspan="2"> </td></tr> <tr><td colspan="2"> </td></tr> <tr><td colspan="2"> </td></tr> <tr><td colspan="2"> </td></tr> <tr><td colspan="2"> </td></tr> <tr><td colspan="2"> </td></tr> <tr><td colspan="2"> </td></tr> <tr><td colspan="2"> </td></tr> <tr><td colspan="2"> </td></tr> <tr><td colspan="2"> </td></tr> <tr><td colspan="2"> </td></tr> <tr> <td colspan="2">RUST of BODY (5: NONE, 4: A LITTLE, 3: MIDDLE, 2: MUCH, 1: CORRODED)</td> </tr> <tr> <td colspan="2">3</td> </tr> </table>	UNDERCARRIAGE See Photos. 写真参照		RUST (5: NONE, 4: A LITTLE, 3: MIDDLE, 2: MUCH, 1: CORRODED)	3	COMMENT														Ripper	MULTI · S/S Shanks PCS	Ripper CYLD.	FAIR · Attn	EQUALIZER BAR	FAIR · Attn	COMMENT		*1 にじみ、メッキ剥がれあり OIL OOZING, COATING: A LITTLE PEELED																												RUST of BODY (5: NONE, 4: A LITTLE, 3: MIDDLE, 2: MUCH, 1: CORRODED)		3	
ENGINE : MODEL	S/N																																																																																																																				
Oil leakage	FAIR · Attn																																																																																																																				
Blow-By	FAIR · Attn A LITTLE · MIDDLE · SEVERE																																																																																																																				
Sound	FAIR · Attn																																																																																																																				
Oil	FAIR · Attn																																																																																																																				
Exhaust Color	FAIR · Attn																																																																																																																				
US EPA	YES · NO																																																																																																																				
OPERATION PUMP																																																																																																																					
Sound	FAIR · Attn																																																																																																																				
Oil leakage	FAIR · Attn																																																																																																																				
Power	FAIR · Attn																																																																																																																				
COOLING SYSTEM																																																																																																																					
Radiator	FAIR · Attn																																																																																																																				
Oil Cooler	FAIR · Attn																																																																																																																				
TRANSMISSION & TRAVEL																																																																																																																					
T/M TYPE	PS · DD DIFF. STEERING YES · NO																																																																																																																				
Transmission	FAIR · Attn																																																																																																																				
Travel	FAIR · Attn																																																																																																																				
INTERIOR See Photos. 写真参照																																																																																																																					
INTERIOR COND.	CLEAN · FAIR · DIRTY																																																																																																																				
Operator's Seat	FAIR · Attn																																																																																																																				
Glasses	FAIR · Attn																																																																																																																				
AirCon	A/C · H/C · H only · C only · None																																																																																																																				
BLADE & CYLINDERS																																																																																																																					
BLADE	FAIR · Attn																																																																																																																				
CYLD.(R)	FAIR · Attn																																																																																																																				
CYLD.(L)	FAIR · Attn *1																																																																																																																				
TILT CYLD	FAIR · Attn																																																																																																																				
ANGLE CYLD	FAIR · Attn																																																																																																																				
UNDERCARRIAGE See Photos. 写真参照																																																																																																																					
RUST (5: NONE, 4: A LITTLE, 3: MIDDLE, 2: MUCH, 1: CORRODED)	3																																																																																																																				
COMMENT																																																																																																																					
Ripper	MULTI · S/S Shanks PCS																																																																																																																				
Ripper CYLD.	FAIR · Attn																																																																																																																				
EQUALIZER BAR	FAIR · Attn																																																																																																																				
COMMENT																																																																																																																					
*1 にじみ、メッキ剥がれあり OIL OOZING, COATING: A LITTLE PEELED																																																																																																																					
RUST of BODY (5: NONE, 4: A LITTLE, 3: MIDDLE, 2: MUCH, 1: CORRODED)																																																																																																																					
3																																																																																																																					

This inspection information is for reference only at "the inspection date" by SOGO. NOT to guarantee the condition of the actual machine.
この査定情報は『点検日時点』での参考資料であり、実際の機械の状態を保証するものではありません。