

INSPECTION SHEET 検品書
EXCAVATOR バックホー

INSPECTION DATE	2025/5/20	MAKE	CAT	MODEL	330CL
SERIAL	CAT0330CLRBH00258			STAMP	CAT0330CLRBH00258
HR METER	26520	HR	YEAR	YR	
CAB/CNP	ROPS CAB / CAB / ROPS CNP / CNP / NONE			SHOE	600FLAT

ENGINE : MODEL		S/N
Oil leakage	FAIR	Attn
Blow-By	FAIR	Attn
Sound	FAIR	Attn
Oil	FAIR	Attn
Exhaust Color	FAIR	Attn
US EPA	YES	NO
MAIN PUMP		
Sound	FAIR	Attn
Oil leakage	FAIR	Attn
Power	FAIR	Attn
COOLING SYSTEM		
Radiator	FAIR	Attn
Oil Cooler	FAIR	Attn
OPERATING SYSTEM		
Swing	FAIR	Attn
Travel	FAIR	Attn
INTERIOR See Photos. 写真参照		
INTERIOR COND.	CLEAN	FAIR
Operator's Seat	FAIR	Attn
Glasses	FAIR	Attn
AirCon	A/C	H/C
BOOM / ARM / BKT		
Boom	FAIR	Attn
Boom Cylinder	FAIR	Attn
Arm	FAIR	Attn
Arm Cylinder	FAIR	Attn
BKT	FAIR	Attn
BKT Cylinder	FAIR	Attn

UNDERCARRIAGE : See Photos. 写真参照	
RUST (5: NONE, 4: A LITTLE, 3: MIDDLE, 2: MUCH, 1: CORRODED)	3
COMMENT	
両側シューリンク固着あり TRACK LINKS: STUCK	
BKT	STD / SLOPE / NARROW / SKELETON (OTHER)
Lever	LONG WRIST
Multi	MULTI 2 NO
ARM-CRANE	YES NO
BLADE	YES NO
OFFSET	YES NO
OFFSET Cylinder	FAIR Attn
Piping	YES NO Breaker only Multi
COMMENT	
エレベータCAB不良 ELEVATOR CAB: MALFUNCTION	
アタッチメント: フォーク付きマグネット ATTACHMENT: MAGNET-FORK	
マグネット一瞬着くがすぐに外れてしまう、	
装置異常警告灯が点灯する(通電ボタン押したらほぼ100%)	
MAGNET: STOPPING TO ATTRACT SOON,	
WARNING LAMP FOR MAGNET DEVICE: ON	
(ALMOST 100% BY TURNING ON THE MAGNET POWER SWITCH)	
両側サイドカバーへコミ大、ラッチ不良	
SIDE COVERS: DEFORMED, LATCHES: MALFUNCTION	
RUST of BODY (5: NONE, 4: A LITTLE, 3: MIDDLE, 2: MUCH, 1: CORRODED)	2

This inspection information is for reference only at "the inspection date" by SOGO. NOT to guarantee the condition of the actual machine.
この査定情報は『点検日時点』での参考資料であり、実際の機械の状態を保証するものではありません。