

INSPECTION SHEET 検品書
EXCAVATOR バックホー

INSPECTION DATE	2025/5/19	MAKE	KOMATSU	MODEL	PC45MR-5
SERIAL	31313		STAMP	KMTPC259HHE031313	
HR METER	5099	HR	YEAR	YR	
CAB/CNP	ROPS CAB / CAB / <u>ROPS CNP</u> / CNP / NONE		SHOE	400G PADS	

ENGINE : MODEL		4D88E	S/N	31285	
Oil leakage	FAIR	Attn			
Blow-By	FAIR	Attn	A LITTLE ・ MIDDLE ・ SEVERE		
Sound	FAIR	Attn			
Oil	FAIR	Attn	油量多い MUCH OIL		
Exhaust Color	FAIR	Attn			
US EPA	YES	NO			
MAIN PUMP					
Sound	FAIR	Attn			
Oil leakage	FAIR	Attn			
Power	FAIR	Attn			
COOLING SYSTEM					
Radiator	FAIR	Attn			
Oil Cooler	FAIR	Attn			
OPERATING SYSTEM					
Swing	FAIR	Attn			
Travel	FAIR	Attn			
INTERIOR See Photos. 写真参照					
INTERIOR COND.	CLEAN	FAIR	DIRTY		
Operator's Seat	FAIR	Attn	破れあり CUT		
Glasses	FAIR	Attn			
AirCon	A/C	H/C	H only	C only	None
BOOM / ARM / BKT					
Boom	FAIR	Attn	ガタあり LOOSE		
Boom Cylinder	FAIR	Attn			
Arm	FAIR	Attn			
Arm Cylinder	FAIR	Attn			
BKT	FAIR	Attn			
BKT Cylinder	FAIR	Attn			

UNDERCARRIAGE :		See Photos. 写真参照	
RUST (5: NONE, 4: A LITTLE, 3: MIDDLE, 2: MUCH, 1: CORRODED)			4
COMMENT			
BKT	STD / SLOPE / NARROW / SKELETON / OTHER ()		
Lever	LONG	WRIST	
Multi	MULTI	2	NO
ARM-CRANE	YES	NO	
BLADE	YES	NO	
OFFSET	YES	NO	
OFFSET Cylinder	FAIR	Attn	
Piping	YES	NO	Breaker only Multi
COMMENT			
L03油圧系統異常警告あり			
“L03” ERROR DISPLAY FOR HYDRAULIC SYSTEM			
ファンベルト鳴きあり FAN BELT: NOISES			
RUST of BODY (5: NONE, 4: A LITTLE, 3: MIDDLE, 2: MUCH, 1: CORRODED)			4

This inspection information is for reference only at "the inspection date" by SOGO. NOT to guarantee the condition of the actual machine.

この査定情報は『点検日時点』での参考資料であり、実際の機械の状態を保証するものではありません。