

INSPECTION SHEET 検品書
EXCAVATOR バックホー

INSPECTION DATE	2025/5/28	MAKE	HITACHI	MODEL	ZX350K-5B
SERIAL	HCMDDDA4J00070327		STAMP	HCMDDDA4J00070327	
HR METER	7691	HR	YEAR	YR	
CAB/CNP	ROPS CAB / CAB / ROPS CNP / CNP / NONE		SHOE	600G	

ENGINE : MODEL		6HK1	S/N	578373
Oil leakage	FAIR	Attn		
Blow-By	FAIR	Attn	A LITTLE	MIDDLE SEVERE
Sound	FAIR	Attn		
Oil	FAIR	Attn		
Exhaust Color	FAIR	Attn		
US EPA	YES	NO		
MAIN PUMP				
Sound	FAIR	Attn		
Oil leakage	FAIR	Attn		
Power	FAIR	Attn		
COOLING SYSTEM				
Radiator	FAIR	Attn		
Oil Cooler	FAIR	Attn		
OPERATING SYSTEM				
Swing	FAIR	Attn		
Travel	FAIR	Attn		
INTERIOR		See Photos. 写真参照		
INTERIOR COND.	CLEAN	FAIR	DIRTY	
Operator's Seat	FAIR	Attn	破れあり CUTS	
Glasses	FAIR	Attn		
AirCon	A/C	H/C	H only	C only None
BOOM / ARM / BKT				
Boom	FAIR	Attn		
Boom Cylinder	FAIR	Attn	*1	
Arm	FAIR	Attn		
Arm Cylinder	FAIR	Attn	油漏れあり OIL LEAKING	
BKT	FAIR	Attn		
BKT Cylinder	FAIR	Attn	傷、にじみあり SCRATCHED, OIL OOZING	

UNDERCARRIAGE :		See Photos. 写真参照	
RUST (5: NONE, 4: A LITTLE, 3: MIDDLE, 2: MUCH, 1: CORRODED)			3
COMMENT			
BKT	STD	SLOPE / NARROW / SKELETON / OTHER (	)
Lever	LONG	WRIST	
Multi	MULTI	2	NO
ARM-CRANE	YES	NO	
BLADE	YES	NO	
OFFSET	YES	NO	
OFFSET Cylinder	FAIR	Attn	
Piping	YES	NO	Breaker only Multi 5
COMMENT			
バックカメラ不良 BACK MONITOR: MALFUNCTION			
*1 左側油漏れ小、右側油漏れあり CYLINDERS: OIL LEAKING			
RUST of BODY (5: NONE, 4: A LITTLE, 3: MIDDLE, 2: MUCH, 1: CORRODED)			3

This inspection information is for reference only at "the inspection date" by SOGO. NOT to guarantee the condition of the actual machine.

この査定情報は『点検日時点』での参考資料であり、実際の機械の状態を保証するものではありません。