

INSPECTION SHEET 検品書
EXCAVATOR バックホー

INSPECTION DATE	2025/5/27	MAKE	HITACHI	MODEL	ZX50U-5B
SERIAL	HCGMAEJA0C00060457			STAMP	HCGMAEJA0C00060457
HR METER	3633	HR	YEAR	YR	
CAB/CNP	ROPS CAB / CAB / ROPS CNP / CNP / NONE			SHOE	400G PADS

ENGINE : MODEL 4TNV88C S/N 29589			
Oil leakage	☐ FAIR · Attn		
Blow-By	☐ FAIR · Attn	A LITTLE · MIDDLE · SEVERE	
Sound	☐ FAIR · Attn		
Oil	☐ FAIR · Attn		
Exhaust Color	☐ FAIR · Attn		
US EPA	☒ YES · NO		
MAIN PUMP			
Sound	☐ FAIR · Attn		
Oil leakage	☐ FAIR · Attn		
Power	☐ FAIR · Attn		
COOLING SYSTEM			
Radiator	☐ FAIR · Attn		
Oil Cooler	☐ FAIR · Attn		
OPERATING SYSTEM			
Swing	☐ FAIR · Attn		
Travel	☐ FAIR · Attn		
INTERIOR See Photos. 写真参照			
INTERIOR COND.	CLEAN · ☒ FAIR · DIRTY		
Operator's Seat	☐ FAIR · Attn	破れあり CUT	
Glasses	FAIR · Attn		
AirCon	A/C · H/C · H only · C only · ☒ None		
BOOM / ARM / BKT			
Boom	☐ FAIR · Attn		
Boom Cylinder	☐ FAIR · Attn		
Arm	☐ FAIR · Attn		
Arm Cylinder	FAIR · ☒ Attn	油漏れあり OIL LEAKING	
BKT	☐ FAIR · Attn		
BKT Cylinder	☐ FAIR · Attn		

UNDERCARRIAGE : See Photos. 写真参照		
RUST (5: NONE, 4: A LITTLE, 3: MIDDLE, 2: MUCH, 1: CORRODED)		3
COMMENT 		
BKT	☒ STD / SLOPE / NARROW / SKELETON / OTHER()	
Lever	LONG · ☒ WRIST	
Multi	☒ MULTI · 2 · NO	
ARM-CRANE	☒ YES · NO	
BLADE	☒ YES · NO	
OFFSET	YES · ☒ NO	
OFFSET Cylinder	FAIR · Attn	
Piping	☒ YES · NO	Breaker only · ☒ Multi
COMMENT 		
RUST of BODY (5: NONE, 4: A LITTLE, 3: MIDDLE, 2: MUCH, 1: CORRODED)		4

This inspection information is for reference only at "the inspection date" by SOGO. NOT to guarantee the condition of the actual machine.

この査定情報は『点検日時点』での参考資料であり、実際の機械の状態を保証するものではありません。