

INSPECTION SHEET 検品書
CRAWLER CRANE クローラクレーン

INSPECTION DATE	2025/5/30	MAKE	SUMITOMO	MODEL	LS78RH5	
SERIAL No.	PLATE : LS078-5004			STAMP	LS078-5004	
HR METER	1512	HR	SHOE	760FLAT	YEAR	YR

ENGINE :		MODEL	H06C	S/N	TB17817
Oil leakage	FAIR	Attn	ヘッドにじみあり CYLINDER HEAD: OIL OOZING		
Blow-By	FAIR	Attn	A LITTLE MIDDLE SEVERE		
Sound	FAIR	Attn			
Oil	FAIR	Attn			
Exhaust Color	FAIR	Attn	黒煙あり BLACK FUMES		
OPERATION PUMP					
Sound	FAIR	Attn			
Oil leakage	FAIR	Attn			
Power	FAIR	Attn			
COOLING SYSTEM					
Radiator	FAIR	Attn			
Oil Cooler	FAIR	Attn			
OPERATING SYSTEM					
Computer	OK	NG	未確認 NOT CHECKED		
Swing	FAIR	Attn			
Travel	FAIR	Attn			
BOOM					
MAIN BOOM		TOP, BOTTOM, 6m × 2, 3m × 1			
BOOM TOTAL		25m			
TOP SHEAVE	YES	NO			
JIB					
TOWER					

INTERIOR		See Photos. 写真参照	
INTERIOR COND.	CLEAN · FAIR · DIRTY		
Operator's Seat	FAIR · Attn		
Glasses	FAIR · Attn		
AirCon	A/C · H/C · H only · C only · None		
UNDERCARRIAGE : See Photos. 写真参照			
RUST (5: NONE, 4: A LITTLE, 3: MIDDLE, 2: MUCH, 1: CORRODED)			3
COMMENT			
WEIGHT		1	
HOOK		35t, BALL	
LIFTER		YES · NO	
COMMENT			
ウインチモーターにじみあり WINCH MOTOR: OIL OOZING			
ボールフック刻印不明 STAMP OF BALL HOOK: UNKNOWN			
@NARITA YARD			
BOOM: TOP, BOTTOM, 6m × 1			
HOOK: 35t, BALL			
@SAKURA YARD			
BOOM: 6m × 1, 3m × 1			
RUST of BODY (5: NONE, 4: A LITTLE, 3: MIDDLE, 2: MUCH, 1: CORRODED)			3

This inspection information is for reference only at "the inspection date" by SOGO. NOT to guarantee the condition of the actual machine.
この査定情報は『点検日時点』での参考資料であり、実際の機械の状態を保証するものではありません。