

INSPECTION SHEET 検品書
EXCAVATOR バックホー

INSPECTION DATE	2025/5/23	MAKE	CAT	MODEL	312
SERIAL	7DK05446		STAMP	7DK05446	
HR METER	UNKNOWN		HR	YEAR	YR
CAB/CNP	ROPS CAB / CAB / ROPS CNP / CNP / NONE		SHOE	700G	

ENGINE : MODEL		S/N
Oil leakage	FAIR · Attn	
Blow-By	FAIR · Attn	A LITTLE · MIDDLE · SEVERE
Sound	FAIR · Attn	
Oil	FAIR · Attn	
Exhaust Color	FAIR · Attn	
US EPA	YES · NO	
MAIN PUMP		
Sound	FAIR · Attn	
Oil leakage	FAIR · Attn	
Power	FAIR · Attn	
COOLING SYSTEM		
Radiator	FAIR · Attn	
Oil Cooler	FAIR · Attn	
OPERATING SYSTEM		
Swing	FAIR · Attn	若干ゴリゴリ感あり A LITTLE RATTLING
Travel	FAIR · Attn	
INTERIOR See Photos. 写真参照		
INTERIOR COND.	CLEAN · FAIR · DIRTY	
Operator's Seat	FAIR · Attn	
Glasses	FAIR · Attn	
AirCon	A/C · H/C · H only · C only · None	
BOOM / ARM / BKT		
Boom	FAIR · Attn	
Boom Cylinder	FAIR · Attn	
Arm	FAIR · Attn	
Arm Cylinder	FAIR · Attn	
BKT	FAIR · Attn	ガタあり LOOSE
BKT Cylinder	FAIR · Attn	

UNDERCARRIAGE :		See Photos. 写真参照
RUST (5: NONE, 4: A LITTLE, 3: MIDDLE, 2: MUCH, 1: CORRODED)		1
COMMENT		
両側ピンブッシュ割れ多数あり MANY PIN BUSHES: BROKEN		
両側トラックローラー不良あり SOME TRACK ROLLERS: MALFUNCTION		
BKT	STD / SLOPE / NARROW / SKELETON / OTHER()	
Lever	LONG · WRIST	
Multi	MULTI · 2 · NO	
ARM-CRANE	YES · NO	
BLADE	YES · NO	
OFFSET	YES · NO	
OFFSET Cylinder	FAIR · Attn	
Piping	YES · NO	Breaker only · Multi
COMMENT		
キーOFFでのE/Gストップ不良(ボタンあり)		
STOPPING THE ENGINE BY KEY: MALFUNCTION		
(ABLE TO STOP THE ENGINE BY SWITCH)		
RUST of BODY (5: NONE, 4: A LITTLE, 3: MIDDLE, 2: MUCH, 1: CORRODED)		1

This inspection information is for reference only at "the inspection date" by SOGO. NOT to guarantee the condition of the actual machine.

この査定情報は『点検日時点』での参考資料であり、実際の機械の状態を保証するものではありません。