

INSPECTION SHEET 検品書
BULLDOZER ブルドーザー

INSPECTION DATE	2025/5/29	MAKE	KOMATSU	MODEL	D21P-8E0
SERIAL	91247			STAMP	KMT0D106EFA091247
HR METER	74	HR	SHOE	510LGP	YEAR YR
BLADE	STRAIGHT / ST/TILT / PAT / ANGLE / OTHER			CAB/CNP	ROPS CAB / CAB / ROPS CNP / CNP / NONE

ENGINE : MODEL		S/N
Oil leakage	☒ FAIR • Attn	
Blow-By	☒ FAIR • Attn	A LITTLE • MIDDLE • SEVERE
Sound	☒ FAIR • Attn	
Oil	☒ FAIR • Attn	
Exhaust Color	☒ FAIR • Attn	
US EPA	YES • ☒ NO	
OPERATION PUMP		
Sound	☒ FAIR • Attn	
Oil leakage	☒ FAIR • Attn	
Power	☒ FAIR • Attn	
COOLING SYSTEM		
Radiator	☒ FAIR • Attn	
Oil Cooler	☒ FAIR • Attn	
TRANSMISSION & TRAVEL		
T/M TYPE	☒ PS • DD	DIFF. STEERING YES • ☒ NO
Transmission	☒ FAIR • Attn	
Travel	☒ FAIR • Attn	
INTERIOR See Photos. 写真参照		
INTERIOR COND.	CLEAN • ☒ FAIR • DIRTY	
Operator's Seat	☒ FAIR • Attn	
Glasses	FAIR • Attn	
AirCon	A/C • H/C • H only • C only • ☒ None	
BLADE & CYLINDERS		
BLADE	☒ FAIR • Attn	
CYLD.(R)	☒ FAIR • Attn	
CYLD.(L)	☒ FAIR • Attn	
TILT CYLD	☒ FAIR • Attn	
ANGLE CYLD	☒ FAIR • Attn	

UNDERCARRIAGE See Photos. 写真参照			
RUST (5: NONE, 4: A LITTLE, 3: MIDDLE, 2: MUCH, 1: CORRODED)			4
COMMENT			
Ripper	MULTI • S/S	Shanks	PCS
Ripper CYLD.	FAIR • Attn		
EQUALIZER BAR	FAIR • Attn		
COMMENT			
パーキング不良 PARKING BRAKE: MALFUNCTION			
RUST of BODY (5: NONE, 4: A LITTLE, 3: MIDDLE, 2: MUCH, 1: CORRODED)			4

This inspection information is for reference only at "the inspection date" by SOGO. NOT to guarantee the condition of the actual machine.
この査定情報は『点検日時点』での参考資料であり、実際の機械の状態を保証するものではありません。