

INSPECTION SHEET 検品書
EXCAVATOR バックホー

INSPECTION DATE	2025/10/10	MAKE	HITACHI	MODEL	ZX225USRK-5B
SERIAL	HCMDCQA2A00306876		STAMP	HCMDCQA2A00306876	
HR METER	13782	HR	YEAR	YR	
CAB/CNP	ROPS CAB / CAB / ROPS CNP / CNP / NONE		SHOE	790G	

ENGINE : MODEL		4HK1	S/N	752574
Oil leakage	(FAIR) · Attn			
Blow-By	(FAIR) · Attn	A LITTLE · MIDDLE · SEVERE		
Sound	(FAIR) · Attn			
Oil	(FAIR) · Attn			
Exhaust Color	(FAIR) · Attn			
US EPA	YES · (NO)			
MAIN PUMP				
Sound	(FAIR) · Attn			
Oil leakage	(FAIR) · Attn			
Power	(FAIR) · Attn			
COOLING SYSTEM				
Radiator	(FAIR) · Attn			
Oil Cooler	(FAIR) · Attn			
OPERATING SYSTEM				
Swing	(FAIR) · Attn			
Travel	(FAIR) · Attn			
INTERIOR		See Photos. 写真参照		
INTERIOR COND.	CLEAN · (FAIR) · DIRTY			
Operator's Seat	FAIR · (Attn)	破れあり CUTS		
Glasses	(FAIR) · Attn			
AirCon	(A/C) · H/C · H only · C only · None			
BOOM / ARM / BKT				
Boom	(FAIR) · Attn			
Boom Cylinder	(FAIR) · Attn			
Arm	(FAIR) · Attn	ガタあり LOOSE		
Arm Cylinder	(FAIR) · Attn			
BKT	(FAIR) · Attn			
BKT Cylinder	(FAIR) · Attn			

UNDERCARRIAGE :		See Photos. 写真参照	
RUST (5: NONE, 4: A LITTLE, 3: MIDDLE, 2: MUCH, 1: CORRODED)		3	
COMMENT			
BKT	(STD) / SLOPE / NARROW / SKELETON / OTHER()		
Lever	LONG · (WRIST)		
Multi	(MULTI) · 2 · NO		
ARM-CRANE	(YES) · NO		
BLADE	YES · (NO)		
OFFSET	YES · (NO)		
OFFSET Cylinder	FAIR · Attn		
Piping	(YES) · NO	Breaker only · (Multi)	
COMMENT			
E/G異常警告表示あり ENGINE WARNING DISPLAY			
RUST of BODY (5: NONE, 4: A LITTLE, 3: MIDDLE, 2: MUCH, 1: CORRODED)		3	

This inspection information is for reference only at "the inspection date" by SOGO. NOT to guarantee the condition of the actual machine.

この査定情報は『点検日時点』での参考資料であり、実際の機械の状態を保証するものではありません。