

INSPECTION SHEET 検品書
EXCAVATOR バックホー

INSPECTION DATE	2024/11/8	MAKE	KUBOTA	MODEL	U-30-5
SERIAL	71644			STAMP	71644
HR METER	5964	HR	YEAR	YR	
CAB/CNP	ROPS CAB / CAB / ROPS CNP / CNP / <u>NONE</u>			SHOE	300R

ENGINE : MODEL		D1703	S/N	9E0160
Oil leakage	<u>FAIR</u> · Attn			
Blow-By	<u>FAIR</u> · Attn	A LITTLE · MIDDLE · SEVERE		
Sound	<u>FAIR</u> · Attn			
Oil	<u>FAIR</u> · Attn			
Exhaust Color	<u>FAIR</u> · Attn			
US EPA	YES · <u>NO</u>			
MAIN PUMP				
Sound	<u>FAIR</u> · Attn			
Oil leakage	<u>FAIR</u> · Attn			
Power	<u>FAIR</u> · Attn			
COOLING SYSTEM				
Radiator	<u>FAIR</u> · Attn			
Oil Cooler	<u>FAIR</u> · Attn			
OPERATING SYSTEM				
Swing	<u>FAIR</u> · Attn	ガタあり SWING: LOOSE		
Travel	<u>FAIR</u> · Attn			
INTERIOR See Photos. 写真参照				
Operator's Seat	FAIR · <u>Attn</u>	破れあり CUTS		
Inside Cover	FAIR · Attn			
Glasses	FAIR · Attn			
AirCon	A/C · H/C · H only · C only · <u>None</u>			
BOOM / ARM / BKT				
Boom	<u>FAIR</u> · Attn			
Boom Cylinder	<u>FAIR</u> · Attn			
Arm	<u>FAIR</u> · Attn			
Arm Cylinder	<u>FAIR</u> · Attn			
BKT	<u>FAIR</u> · Attn	ガタあり LOOSE		
BKT Cylinder	<u>FAIR</u> · Attn			

UNDERCARRIAGE : See Photos. 写真参照	
RUST (5: NONE, 4: A LITTLE, 3: MIDDLE, 2: MUCH, 1: CORRODED)	4
COMMENT	
BKT	<u>STD</u> / SLOPE / NARROW / SKELETON / OTHER ()
Lever	LONG · <u>WRIST</u>
Multi	<u>MULTI</u> · 2 · NO
ARM-CRANE	YES · <u>NO</u>
BLADE	<u>YES</u> · NO
OFFSET	YES · <u>NO</u>
OFFSET Cylinder	FAIR · Attn
Piping	YES · <u>NO</u> Breaker only · Multi
COMMENT	
RUST of BODY (5: NONE, 4: A LITTLE, 3: MIDDLE, 2: MUCH, 1: CORRODED)	3

This inspection information is for reference only at "the inspection date" by SOGO. NOT to guarantee the condition of the actual machine.
この査定情報は『点検日時点』での参考資料であり、実際の機械の状態を保証するものではありません。