

INSPECTION SHEET 検品書
EXCAVATOR バックホー

INSPECTION DATE	2025/7/23	MAKE	HITACHI	MODEL	EX70LCK-5
SERIAL	1C2P054074		STAMP	1C2P054074	
HR METER	6169	HR	YEAR	2000	YR
CAB/CNP	ROPS CAB / CAB / ROPS CNP / CNP / NONE		SHOE	450G PADS	

ENGINE : MODEL	S/N
Oil leakage	FAIR · Attn
Blow-By	FAIR · Attn A LITTLE · MIDDLE · SEVERE
Sound	FAIR · Attn
Oil	FAIR · Attn
Exhaust Color	FAIR · Attn
US EPA	YES · NO

MAIN PUMP

Sound	FAIR · Attn	
Oil leakage	FAIR · Attn	
Power	FAIR · Attn	

COOLING SYSTEM

Radiator	FAIR · Attn	
Oil Cooler	FAIR · Attn	

OPERATING SYSTEM

Swing	FAIR・Attn	ガタあり SWING: LOOSE
Travel	FAIR・Attn	

INTERIOR See Photos. 写真参照

INTERIOR COND.	CLEAN ▪ FAIR ▪ DIRTY				
Operator's Seat	FAIR ▪	Attn			
Glasses	FAIR ▪	Attn			
AirCon	A/C ▪	H/C ▪	H only ▪	C only ▪	None

BOOM / ARM / BKT

Boom	FAIR	Attn	
Boom Cylinder	FAIR	Attn	
Arm	FAIR	Attn	*1
Arm Cylinder	FAIR	Attn	
BKT	FAIR	Attn	
BKT Cylinder	FAIR	Attn	シリンダー動作部分に塗着あり PAINTY

UNDERCARRIAGE : See Photos. 写真参照

RUST (5: NONE, 4: A LITTLE, 3: MIDDLE, 2: MUCH, 1: CORRODED)	3
---	----------

COMMENT

BKT	STD / SLOPE / NARROW / <u>(SKELETON)</u> / OTHER()
-----	---

Lever	LONG ▪ WRIST	
-------	--------------	--

Multi	MULTI • 2 • NO
-------	----------------

ARM-CRANE	YES	☒ NO
-----------	-----	-------------------------------------

BLADE	☒ YES • ☐ NO
-------	---

OFFSET	YES • NO
--------	----------

OFFSET Cylinder	FAIR ▪ Attn	
-----------------	-------------	--

Piping	YES ▪ NO	Breaker only ▪ Multi
--------	-----------------	-----------------------------

COMMENT

SOME HOSE AROUND LOWER PART OF BOOM: CRACKED

A/C冷えない A/C: MALFUNCTION

*1 スライドアーム、スライド部ガタあり

*1 SLIDE ARM (LENGTH: 7.7m), SLIDE PART: LOOSE

.....

.....

.....

.....

.....

BLIST of BODY (5: NONE 4: A LITTLE 3: MIDDLE 2: MUCH 1: CORRODED)	3
---	---

This inspection information is for reference only at "the inspection date" by SOGO. NOT to guarantee the condition of the actual machine.

この査定情報は『点検日時点』での参考資料であり、実際の機械の状態を保証するものではありません。