INSPECTION SHEET 検品書 CARRY DUMP キャリーダンプ

INSPECTION DA		2025/5/14	MAKE	N	//OROOKA		MODEL	MST-2200VD		
SERIAL	222300				STAMP		222300			
HR METER	3237 HR Odometer					ŀ	m YEAR			YR
CAB/CNP	ROPS CA	AB CAB ROP	S CNP / CNP /	/ NONE	SHOE		730R	TIRE		
ENGINE :	MAIN FRAME									
Oil leakage	FAIR · Attn			MAIN FLAME FAIR - Attn						
Blow-By	FAIR · Attn	A LITTLE · MIDDL		VESSEL						
Sound	FAIR · Attn				VESSE	L	FAIR • Attn	*1		
Oil	FAIR · Attn				REAR GATE	TYPE	NORMAI	_ • L-	GATE (FLAT)	
Exhaust Color	FAIR · (Attn	白煙あり WHITE	FUMES		REAR GA	ATE	FAIR • Attn			
US EPA	YES)· NO				UNDERCARRIAGE: See Photos. 写真参照					
OPERATION PUMP					RUST (5: NONE, 4: A LITTLE, 3: MIDDLE, 2: MUCH, 1: CORRODED) 4					
Sound	FAIR · Attn				TIRE WE	AR	FAIR • W	ORN · UI	NEVEN WEAR	
Oil leakage	FAIR · Attn				COMMENT	Γ				
Power	FAIR · Attn				左右トラック	フレーム	ム割れあり T	RACK FRA	MES: MUCH CR	ACKED
COOLING SYSTEM					バッテリー液警告灯点灯あり WARNING LAMP FOR BATTERY FLUID					
Radiator	FAIR · Attn				*1 クラック	、ヘコ	ミあり CRA	CKED, A	LITTLE DEFO	RMED
Oil Cooler	FAIR · Attn									
TRANSMIS										
T/M TYPE	PS) · DD		No. OF GEARS 2	GEARS						
Transmission	FAIR · Attn									
Travel	FAIR · Attn									
Swing	FAIR · Attn									
Articulate	FAIR · Attn									
FOOT BRAKE	FAIR · Attn									
PARKING BRAKE	FAIR · Attn									
INTERIOR See Photos. 写真参照										
INTERIOR COND.	CLEAN	· FAIR ·	DIRTY							
Operator's Seat	FAIR · Attn									
Glasses	FAIR · Attn									
AirCon	A/C).	H/C • H only	• C only •	None	RUST of BODY	(5: NONE	, 4: A LITTLE, 3: N	MIDDLE, 2: MU	CH, 1: CORRODED)	4

This inspection information is for reference only at "the inspection date" by SOGO. NOT to guarantee the condition of the actual machine. この査定情報は『点検日時点』での参考資料であり、実際の機械の状態を保証するものではありません。