

INSPECTION SHEET 検品書
EXCAVATOR バックホー

INSPECTION DATE	2025/8/22	MAKE	KOMATSU	MODEL	PC78US-8
SERIAL	26998		STAMP	KMTPC213VEA026998	
HR METER	4260	HR	YEAR	YR	
CAB/CNP	ROPS CAB / CAB / ROPS CNP / CNP / NONE		SHOE	600G	

ENGINE : MODEL 4D95LE-5 S/N 00556370	
Oil leakage	FAIR • Attn
Blow-By	FAIR • Attn A LITTLE • MIDDLE • SEVERE
Sound	FAIR • Attn
Oil	FAIR • Attn
Exhaust Color	FAIR • Attn
US EPA	YES (NO)
MAIN PUMP	
Sound	FAIR • Attn
Oil leakage	FAIR • Attn
Power	FAIR • Attn
COOLING SYSTEM	
Radiator	FAIR • Attn
Oil Cooler	FAIR • Attn
OPERATING SYSTEM	
Swing	FAIR • Attn
Travel	FAIR • Attn
INTERIOR See Photos. 写真参照	
INTERIOR COND.	CLEAN • FAIR • DIRTY
Operator's Seat	FAIR • Attn
Glasses	FAIR • Attn
AirCon	(A/C) • H/C • H only • C only • None
BOOM / ARM / BKT	
Boom	FAIR • Attn
Boom Cylinder	FAIR • Attn
Arm	FAIR • Attn
Arm Cylinder	FAIR • Attn
ATTACHMENT	FAIR • Attn
BKT Cylinder	FAIR • Attn

UNDERCARRIAGE : See Photos. 写真参照	
RUST (5: NONE, 4: A LITTLE, 3: MIDDLE, 2: MUCH, 1: CORRODED)	3
COMMENT	
BKT	(STD) / SLOPE / NARROW / SKELETON / OTHER ()
Lever	LONG • (WRIST)
Multi	(MULTI) • 2 • NO
ARM-CRANE	(YES) • NO
BLADE	(YES) • NO
OFFSET	YES • (NO)
OFFSET Cylinder	FAIR • Attn
Piping	YES • (NO) Breaker only • Multi
COMMENT	
RUST of BODY (5: NONE, 4: A LITTLE, 3: MIDDLE, 2: MUCH, 1: CORRODED)	
3	

This inspection information is for reference only at "the inspection date" by SOGO. NOT to guarantee the condition of the actual machine.
 この査定情報は『点検日時点』での参考資料であり、実際の機械の状態を保証するものではありません。